

WELL COMPLETION LOG

Form 22-5 (Rev. 2-62)

Page 2

(Show details of tubular goods, bottom hole accessories, DST's, Cores, Deviations, and General Chronological History).

Plug and Abandonment

3-24-81 Pulled 71 joints of 1" linepipe tubing.
Set 5 1/2" HOWCO B.P. @1458'. Shot one hole at 650'. Ran 47
joints 2 3/8" EUE tubing and tagged B.P.
Halliburton circulated hole with 27 bbls. F.L. @1134'.
Pumped 10 sacks bottom plug on top of B.P.
Pulled 26 joints and spotted 25 sacks and squeezed with 5 (10
sack ea.) plugs. (Cement returned to surface behind pipe).
Pulled tubing to 150' and circulated cement to surface.