

## OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Wood
9. Well No. 1
10. Field and Pool, or Wildcat Aztec Fruitland
12. County San Juan

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
Name of Operator Meridian Oil Inc.
Address of Operator PO Box 4289, Farmington, NM 87499
Location of Well UNIT LETTER N 990 FEET FROM THE South LINE AND 1650 FEET FROM THE West LINE, SECTION 14 TOWNSHIP 29N RANGE 11W N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)  
5509' GL.Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>


7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is intended to plug &amp; abandon this well in the following manner:

MOL&RU. POOH replacing bad jts. of 1" tbq. TIH, circulate wellbore full w/9 ppg mud. (gel 25 sx/10 bbls.). Spot 20 sx (24 cu.ft.) cmt. plug from TD to 1465' to cover Fruitland and 5 1/2" csg. shoe. POOH. WOC. TIH, tag top of plug. Spot 60 sx (71 cu.ft.) cmt. plug from 525' to surface to cover Ojo Alamo @ 475'. POOH. Cut off wellhead. Install dry hole marker w/10 sx.

**RECEIVED**  
JUN 15 1988  
OIL CON. DIV  
DIST. 3

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Drilling Clerk (WS)	DATE June 13, 1988
Original Signed by CHARLES GHOLSON	DEPUTY OIL & GAS INSPECTOR, DIST. #3	JUN 15 1988
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		