

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved,
Budget Bureau No. 42 B-494
5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-2199

6. IF INDIAN ALLOTTEE OR TRIBE NAME

Navajo

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen a plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injection Well

2. NAME OF OPERATOR
Humble Oil & Refining Company

3. ADDRESS OF OPERATOR
P. O. Box 120, Denver, Colorado 80201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

SWSE(660' FSL & 1830' FEL) of Section 16

7. UNIT ASSIGNMENT NAME
Northwest Cha Cha

8. FARM OR LEASE NAME
Northwest Cha Cha Unit

9. WELL NO.
34-16

10. FIELD AND FOOT, OR WHDCAT
Cha Cha Gallup

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA
Sec 16-29N-14W NMPM

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
5192' KB

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1-11-72 - Spot 10 sack cement plug 4735-4835', 10 sack plug 4220-4120'.

1-13-72 - Shot and pulled 4 1/2" casing from 1260'. Spot 30 sack cement plug 850-750', 30 sack cement plug 610-510', 35 sack cement plug 257-157'. Installed regulation dry hole marker in top of surface casing with 12 sack cement plug from 30-0'.
Intervals between plugs filled with mixed mud.


2-7-72 - Location cleaned ready for inspection.

cc: 2 - NM O&G Commission

1 - Minerals Supervisor - Navajo Tribe

1 - Midland

1 - Clinton



FEB 1 1972

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Dist. Superintendent

DATE

2-9-72

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: