

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. 14-20-0603-6377
2. NAME OF OPERATOR Bumble Oil & Refining Co.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME None
3. ADDRESS OF OPERATOR P. O. Box 120 Denver, Colorado 80201	7. UNIT AGREEMENT NAME None
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface SW 1/4 (990' PUL & 983' PUL) Sec. 18-23-15N	8. FARM OR LEASE NAME Harajo tract 2
14. PERMIT NO.	9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5347' DF	10. FIELD AND POOL, OR WILDCAT South Water flow
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 18-23-15N
	12. COUNTY OR PARISH San Juan
	13. STATE N. Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 11,165' - PSTD 4,121'.

Well plugged and abandoned as follows:

25 sacks cement across perforations 4109-14'.

When preparing to pull 7" casing found gas flow coming out between 9 5/8" surface casing and 7" casing. Did not cut and pull 7" casing.

Pumped 300 sacks grade A cement plug between 9 5/8" and 7" at 600# pressure. Placed 30 sacks cement plug inside 7" casing 1500-1700'.

Placed 30' surface plug in 7" with regulation marker. Intervals between plugs in 7" filled with mud. Plugging complete 1-4-67.

Location cleaned, pits filled and ready for inspection.



RECEIVED

JAN 31 1967

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED Original signed by: Roger S. Frazier

TITLE Dist. Oper. Supt.

DATE 1-24-66

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____