

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

(Other instructions on reverse side)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. SF-077710
2. NAME OF OPERATOR R & G DRILLING CO.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR c/o Walsh Engineering & Prod. Corp. P. O. Box 254, Farmington, New Mexico 87401		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1850'FSL, 1120'FEL		8. FARM OR LEASE NAME Hardie
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5730'GL		10. FIELD AND POOL, OR WILDCAT Fulcher Kutz P. C.
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 14-T29N-R12W N.M.P.M.
		12. COUNTY OR PARISH San Juan
		13. STATE New Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	FULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

2-25-77

This well was plugged and abandoned in the following manner.

1. Set 35 sack cement plug 1826'-1700'.
2. Perforate 4 holes at 750'.
3. Set 65 sack cement plug in and out of casing 550' to 750'.
4. Set 10 sack surface plug with dry hole marker.



RECEIVED
APR 14 1977
U. S. GEOLOGICAL SURVEY

For: R&G Drilling Co.

18. I hereby certify that the foregoing is true and correct

SIGNED Ewell N. Walsh, P. E.

President, Walsh Engineering &

TITLE Production Corp.

DATE 4/13/77

(This space for Federal or State office use)

APPROVED BY P. J. McGrath
CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

JUN 8 1978

P. J. McGRATH

DISTRICT ENGINEER

*See Instructions on Reverse Side