

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

|  |  |   |                             |
|--|--|---|-----------------------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>   |  | 5. LEASE DESIGNATION AND SERIAL NO.<br><b>14-20-0603-6377</b>             |                             |
| 2. NAME OF OPERATOR<br><b>Humble Oil &amp; Refining Company</b>  |  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME<br><b>Navajo</b>                     |                             |
| 3. ADDRESS OF OPERATOR<br><b>P. O. Box 120, Denver, Colorado 80201</b>   |  | 7. UNIT AGREEMENT NAME<br><b>Navajo Trust 2A</b>                          |                             |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br><b>NE 1/4 Sec. 18-29N-15W</b> |  | 8. FARM OR LEASE NAME<br><b>Navajo Trust 2A</b>                           |                             |
| 14. PERMIT NO.   |  | 9. WELL NO.<br><b>3</b>   |                             |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br><b>5404' DF</b>  |  | 10. FIELD AND POOL, OR WILDCAT<br><b>North Waterflow</b>                  |                             |
|  |  | 11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA<br><b>Sec. 18-29N-15W</b> |                             |
|  |  | 12. COUNTY OR PARISH<br><b>San Juan</b>                                   | 13. STATE<br><b>N. Mex.</b> |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

|  |   |
|--|---|
| TEST WATER SHUT-OFF <input type="checkbox"/> | PULL OR ALTER CASING <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/>      | MULTIPLE COMPLETE <input type="checkbox"/>    |
| SHOOT OR ACIDIZE <input type="checkbox"/>    | ABANDON* <input checked="" type="checkbox"/>  |
| REPAIR WELL <input type="checkbox"/>         | CHANGE PLANS <input type="checkbox"/>         |
| (Other) <input type="checkbox"/>             |   |

SUBSEQUENT REPORT OF:

|  |  |
|--|--|
| WATER SHUT-OFF <input type="checkbox"/>        | REPAIRING WELL <input type="checkbox"/>  |
| FRACTURE TREATMENT <input type="checkbox"/>    | ALTERING CASING <input type="checkbox"/> |
| SHOOTING OR ACIDIZING <input type="checkbox"/> | ABANDONMENT* <input type="checkbox"/>    |
| (Other) <input type="checkbox"/>               |  |

(Note: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

**TD 4,265', FRED 4,238'.**

**Humble proposes to plug and abandon as follows:**

Place 25 sacks cement over and squeeze small amount of cement into perforations 4,178-93'.  
Cut 4 1/2" casing at approximately 3,300' and pull.  
100' plug across 4 1/2" casing stub with 25 sacks.  
100' plug 850-950' with 25 sacks.  
15' surface plug with regulation marker.  
Intervals between plugs will be filled with mud, location cleaned and pits filled.

18. I hereby certify that the foregoing is true and correct

SIGNED Original signed by: Roger S. Frazier

TITLE Dist. Operations Supt.


DATE October 26, 1966

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

\*See Instructions on Reverse Side



U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.