UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sun	dry Notices and Reports on Wel	lls	
1. Type of Well GAS	DECEIVED APR 1 8 1994	6.	Lease Number SF-077317 If Indian, All. or Tribe Name Unit Agreement Name
4. Location of Well, Foo	f Operator ton, NM 87499 (505) 326-9700	9. - 10.	Well Name & Number Cooper #1 API Well No. Field and Pool Fulcher Kutz PC County and State San Juan Co, NM
12. CHECK APPROPRIATE BO Type of Submission _x_ Notice of Inte Subsequent Reg Final Abandons	Recompletion Plugging Back Casing Repair	rtion .	
The subject well was evaluated for casing integrity; current tubing/casing pressure are 150 and 150 respectively, indicating integrity for the wellbore is sound and no remedial action is currently required. The subject well is currently non-productive due to excessively high line pressure. Should line pressure drop sufficiently, this well will produce in economic quantities. We are currently evaluating options to reduce line pressure in general, and allow the subject well to once again produce in economic quantities. MAY 0.1 1005			
14. I hereby certify t	MAY 01 1995 hat the foregoing is true and (SBD) Title Regulatory A		3: 07 et.
(This space for Federal APPROVED BY CONDITION OF APPROVAL,	Title		PROVED