



P. O. BOX 1058
BLOOMFIELD, N. M. 87413
505-632-3392

August 29, 1986

Invoice # D 4260

New Mexico Oil Conservation Commission
District III Office
1000 Rio Brazos
Aztec, New Mexico 87410

LOCATION: Umbenhour #1

Contract #8-75-06

08/04/86 Drove to location, unload backhoe, remove fence, brush and other obstructions from area where well site is supposed to be. 8 Hours.

08/05/86 Drove to location, unload dozer. Continue to search for well with dozer, backhoe and metal detector. 9 Hours.

08/06/86 Drove to location, continue to search area, digging down 10 to 12 feet with no signs of well. 9 Hours.

08/07/86 Drove to location, continue to search area, found well site at 11:30am. Dug around well with backhoe, cut off 13" pipe with wooden plug inside. Weld on 8' piece of 8 5/8" casing. Cover hole and prepare location for arrival of rig and equipment.

08/11/86 Road rig to location and rig up. Install well control equipment, pick up power swivel and 1 joint of 2 3/8" tubing, 1-4 3/4 bit. Go in hole to 18', tagged plug. Start drilling operations, shut down.

08/12/86 Drove to location, start rig, go in hole 18' to plug, start drilling. Drill out plug to 60', Wood and Hydromite or cement plug. Shut down.

08/13/86 Drove to location, lay swivel down and start picking up tubing, found another plug at 458'. Drill out 45' to 503', shale and sand. Lay swivel down, pick up 3 joints, tag 3rd plug at 596'. Shut down.

08/14/86 Drove to location, service rig and equipment. Pick up power swivel and start washing to bottom. Plugged bit at 1466', pull out of hole, unplug bit and go back in hole. Washed 32', plug bit again, trip out hole, unplug bit, trip back to bottom, 60' off bottom, shut down and mix mud. Condition hole, circulate shale and sand out. Trip out of hole. Shut down. Surface pipe washing out, Depth 1466'.

08/15/86 Drove to location, mix 15 sacks of ready mix cement and pour around surface casing while waiting on cement we mixed mud and trip in hole. Run notched collar on bottom, washed 4 joints down, circulate hole clean and pull 4 stands. Shut down. Depth 1466'.



P. O. BOX 1058
BLOOMFIELD, N. M. 87413
505-632-3392

August 29, 1986

Invoice # D 4260

New Mexico Oil Conservation Commission
District III Office
1000 Rio Brazos
Aztec, New Mexico 87410

LOCATION: Umbenhour #1

Contract #8-75-06

08/18/86 Drove to location, rig up swivel, wash 4 stands to bottom 1466'. Circulate hole getting large amounts of sand and shale, hole caving off, pull 3 stands, lay 9 joints down. Shut down.

08/19/86 Drove to location, run 7 stands to bottom 1466'. Circulate hole, mix and spot 70 sacks of cement with 3% calcium chlorides. Wait on cement 3½ hours. Trip in hole and tag cement at 1280', mix and spot 70 more sacks of cement 3% calcium chlorides. Wait on cement 2½ hours. Trip in hole, found no cement down to 495', pull out of hole and shut down.

08/20/86 Drove to location, service rig. Trip in hole, tag cement at 503', pull 1 joint, mix and spot cement from 471' to surface. Pull tubing and rig down.

08/21/86 Drove to location, back drag location, install dry hole marker, rebuild ditch to orchard, fence orchard where fence had been removed and remove road. Put in water diversions, leave location as close to original as possible.

AS PER BID----- \$16,685.00

5.25% NM Tax---- \$16,685.00
875.96

Total----- \$17,560.96

Less Discount
\$16,962.57

THANK YOU.