		Form approved,
Form 9-331 (May 1963)	UNITED STATES SUBMIT IN TRIPLICATES (Other instructions on re	Rudget Rurenn No. 42-R1424.
	DEPARTMENT OF THE INTERIOR verse side)	5F 0655 7
	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	NDRY NOTICES AND REPORTS ON WELLS	
(Do not use th	us form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	
1.		7. UNIT AGREEMENT NAME
OIL GAS WELL	OTHER	
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
PRODUCI	NG ROYALTIES / NC.	CORNECC
3. ADDRESS OF OPERAT	MOR.	9. WELL NO.
Box 1021	(Report location clearly and in accordance with any State requirements.*	12
See also space 17 t	(Report location clearly and in accordance with any State requirements.* nelow.)	10. FIELD AND POOL, OR WILDCAT
At surface	in & 990 fer Sec. 11, T29N RIZW	11. SEC., T., B., M., OR BLK. AND
		SURVEY OR AREA
5	AN JUAN CO., N.M.	Sec 11, T 29N, R12L
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH   13. STATE
	5718	SAN JUAN NM
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or C	
	NOTICE OF INTENTION TO:	UENT REPORT OF:
TEST WATER SHUT	F-OFF FULL OR ALTER CASING WATER SHUT-0FF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON* SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS (Other) (Note: Report result	s of multiple completion on Well
(Other)	Completion or Recomp	oletion Report and Log form.)
proposed work.	OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates If well is directionally drilled, give subsurface locations and measured and true vertices.)	cal depths for all markers and zones perti-
nent to this work	T was book of any for I	~ /:
	THIS WELL HAS been discovered from seator INTENDS to Plug and ABANDON	SALES LINE.
Ope	SEATOR INTENDS to Plug and ARRIVAN	this WELL BE
•	= 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	11113 55662 113
tor	Lows:	
	<u>.</u>	1
1-	Spot Cement Plug from 1899 To	to 17 <b>60</b>
Z.	Cut & Pull 7" CASING	
		0 - 1 :
₹.	Spot Plug 50' in \$50' Abo	ue (sa Stub
•		Semily The
26	- + Plu 700' to 500'	
7.	Spot Plug 700' to 550	
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
5.	Set PAA MARKER W/ 108%	
	_	•
6.	CLEAN LOC.	<b>₹</b>
_		·
18. I hereby certify th	nat the foregoing is true and correct	_
	Brown for Dona	to 2000 1400 7 1979

(This space for Federal or State office use) DATE \_ TITLE .

Olal