

A brief history of the Carroll & Cornell
Cornell #9, L-12-29N-12W

The well was drilled on Federal land between December 19, 1946 and April 27, 1948 and has never produced. It was drilled to 4240' in the Point Lookout and is not cemented from the bottom of the Pictured Cliffs about (2000') to surface. There are several domestic water wells within a radius of 2 miles, which contain gas and are unusable. I believe the Cornell #9 has a casing failure and is causing or contributing to the problem.