

Form 10-1  
May 1908

AR

1001

(SUBMIT IN TRIPLICATE)

U. S. Head Office, SANTA FE N. M.

UNITED STATES

Local or District No. 069557

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

|                                                |                                                                                |
|------------------------------------------------|--------------------------------------------------------------------------------|
| NOTICE OF INTENTION TO DRILL                   | SUBSEQUENT REPORT OF WATER SHUT-OFF                                            |
| NOTICE OF INTENTION TO CHANGE PLANS            | <input checked="" type="checkbox"/> SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF     | SUBSEQUENT REPORT OF ALTERING CASING                                           |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR                                      |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE        | SUBSEQUENT REPORT OF ABANDONMENT                                               |
| NOTICE OF INTENTION TO PULL OR ALTER CASING    | SUPPLEMENTARY WELL HISTORY                                                     |
| NOTICE OF INTENTION TO ABANDON WELL            |                                                                                |

INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA:

June 23

19 47

Well No. 9 is located 1650 ft. from line and 330 ft. from line of sec. 12

7. 12. 12

29

12.1

XXXX

FOOTING

JAN. 1948

NEW MEXICO

The elevation of the derrick floor above sea level is 5775 ft.

### DETAILS OF WORK

Describe in detail the work done in this well, including the nature of the work, the results obtained, and the nature of the work proposed.

According to our latest conversation of the 22nd, - with change in for cement in pipe on top of 1 - joint look-out and stone which was encountered at 4240'; pipe is now set at 4205', getting a perfect water shut-off, but is stuck so tight that it is impossible to pull it to cement, in spite of all efforts to do so. - called 43" tension on the line and worked it for two hours, but it is still bottom with trip spear and in blind move it, so as to be allowed to drill sand and oil and oil is encountered in concrete and cement in this way.

Information for this report of work must receive approval in writing by the Geological Survey before operations may be discontinued.

Company: ...

Location: ...

By: ...

Title: ...