

U.S. GOVERNMENT
PRINTING OFFICE

U.S.G.S. IN TRIPPLICATED

U.S. LAND OFFICE

SANTA FE

Land - Report No. 065552

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

- NOTICE OF INTENTION TO DRILL
- NOTICE OF INTENTION TO CHANGE PLANS
- NOTICE OF INTENTION TO TEST WATER SHUT OFF
- NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL
- NOTICE OF INTENTION TO SHOOT OR ACIDIZE
- NOTICE OF INTENTION TO PULL OR ALTER CASING
- NOTICE OF INTENTION TO ABANDON WELL

- SUBSEQUENT REPORT OF WATER SHUT-OFF
- SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
- SUBSEQUENT REPORT OF ALTERING CASING
- SUBSEQUENT REPORT OF REDRILLING OR REPAIR
- SUBSEQUENT REPORT OF ABANDONMENT
- SUPPLEMENTARY WELL HISTORY

INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE OR OTHER DATA

Feb 21,

1947

Well No. 9 is located 1650 ft from $\frac{1}{4}$ line and 330 ft from $\frac{1}{4}$ line of sec 12

Section 28-42

22. 126.

NW 1/4

Bulcher Basin

San Juan

New Mexico.

The elevation of the derrick floor above sea level 5773

DETAILS OF WORK

(Indicate the number of expected trips to the surface, number, size, weight, and length of proposed casings, indicate including other factors, the points, and all other important proposed work)

Following is a description of the twentieth job

This is the small amount of gas encountered in the Picture Cliff, the gas was found at 10 of the trip 17 through the Lower Cliff, instead of continuing to the top of the bed.

RECEIVED

81

2/22/47

Information concerning the above work must receive approval by the Geological Survey before operations may be commenced.

Compt. C. L. Marshall

C. L. Marshall

2/22/47

Marshall, C. L.
Proprietor, New Mexico.

By C. L. Marshall
Title Owner