

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

May 7, 1965

J. Glenn Turner
1900 Mercantile Dallas Building
Dallas 1, Texas

Re: 1964 Annual Packer Leakage
Test, #9 Nye, 9-29N-10W

Gentlemen:

Our records reflect that the above dually completed well developed communication between the producing zones and was repaired on March 13, 1964. However, we have not received a packer leakage test run subsequent to the workover.

Will you please determine if the test was conducted and if so, submit the results on the Commission packer leakage test form. If it was not retested, please schedule the well for packer leakage test immediately.

Yours very truly

Emery C. Arnold
Supervisor, District #3

ECA:ks

OIL CONSERVATION COMMISSION
1000 RIO BRAVO ROAD
AZTEC, NEW MEXICO

Page 10 of 10

Enclosed for the
Commissioner of the
Department of Energy

Enclosed for the
Commissioner of the
Department of Energy

Enclosed for the

Enclosed for the
Commissioner of the
Department of Energy
Enclosed for the
Commissioner of the
Department of Energy

Enclosed for the
Commissioner of the
Department of Energy
Enclosed for the
Commissioner of the
Department of Energy

Enclosed for the

Enclosed for the
Commissioner of the
Department of Energy

Enclosed for the