

P. O. Box 2078
Farmington, New Mexico

May 24, 1962

New Mexico Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico

Gentlemen:

Please find attached a re-test for packer leakage on our Nye #9-1 well.

A test of the wellhead indicated the presence of a small wellhead leak. Correction of this seems to have resulted in a satisfactory test. This test was made through a separator.

Also, find attached a service company report showing the pressure recorded on a BHP bomb which was run at 4180'.

Yours truly,

J. GLENN TURNER

Albert S. Johnson
Albert S. Johnson
Petroleum Engineer

m:
Encl

