## (SUBMIT IN TRIPLICATE)

## UNITED STATES ENGINE DEPARTMENT OF THE INTERIOR

Land Office	Santa Po
Lease No	077092
	# m ub

**GEOLOGICAL SURVEY** 

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL  NOTICE OF INTENTION TO CHANGE PLANS  NOTICE OF INTENTION TO TEST WATER SHUT-OFF  NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	 SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	 SUBSEQUENT REPORT OF ABANDONMENT

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


		***************************************	October 25	, 19 <b>.53</b> .
Well Nois located		from $\begin{bmatrix} N \\ C \end{bmatrix}$ line and	1550 ft. from $\{E\}$ line of sec	. 12
ME Section 12	258	104	H. M. P. M.	
(1/2 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
Elanco-La Plata	9	In June	Mare Manual and	
(Field)	(Co	unty or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is 5766... ft.

## **DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

This well was re-tasted after workover. Open flow 2,480 MEF/b, SEPT 1104 paig.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced

Company Il. Jaco Interel des Company	
Address Doe 997	21111
Farmington, Bow Musico	By J. J. Takkey
	Title Petrolem Ingleser.

and the second of the second o and the second of the second o ر المراجع المر المراجع المراجع