MERGY AND MIN	NERALS DEPARTMEN	17							
	40001469	011	L CONSERVA	TION D	IVISION				
	P. O. BOX 2088						Form C-103		
SANTA FE		S	ANTA FE, NEW	MEXICO	87501			Revised 1	
U.S.G.S.						Sa. Ir	adicate Type	of Letse	
LAND OFFIC	:E			•	4	1	tate		X
PERATOR						5. St	ate Oil is Gas		€
				 -	- 3				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN ON PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)									
**ELL	GAS X	GTHER-				7. Un	it Agreement	Name	7777
Meridian Oil Inc.							8. Farm or Lease Name McClure		
Address of Operator							il No.		
PO Box 4289, Farmington, NM 87499							1		
Location of Well						10. F	ieid and Poo	i, or Wildcat	
WHIT LETTER	99	10 . FEET P	South	LINE AND _	1650	AZ	tec Pic	Cliffs	5
Fas	: †	3	291 TOWNSHIP	V	1 1 W		///////		
THE	LINE, SECTION		TOWNSHIP	RANGE		NMPM.			
mm	mmm	////// 15 E1	ermion (Shoromiasias	DE PT CP			7777777	777777	7777
			evation (Show whether	br, KI, GK.	5674'GL	San	Juan		
	Check A	ppropriate B	ox To Indicate N	ature of N	otice. Report o	or Other Da			
Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO: SUBSEQUENT									.7
					_	_			
MFORM REMEDIAL	=	•	PLUG AND ABANDON	REMEDIAL WO	DAX	=	ALTERIS	NG CASING	
MPORARILY ABAND			r		TILLING OPHS.	4	PLUG AN	D ABANDONMEN	٠٠ 🔲
LL OR ALTER CAS	ING	c	HANGE PLANS	CASING TEST	AND CEMENT JOB				_
OTHER	Recomp1e	ete		OTHER					_ []
OTHER									
Describe Propos	sed or Completed Ope	rations (Clearly	state all pertinent deta	ils, and give	pertinent dates, inc	luding estima	ted date of si	arting any pro	posed
work) SEE RUL	. 2 , 103.								
			abandon the l land Coal se					recomple	ete
						_			
			aluate casin						
-			nole logs.						
			rmation unde						SX
			18 cu.ft., 1						
•	treat the	ruitland	d Coal forma	tion .	Produce w	ell thr	ough 1	1/2".tl	bg.
	If wellbore	e is not	competent (determi	ned from e	valuati	on abo	ve), the	е
	well will	se plugge	ed and aband	oned as	follows:			-,,	-
	Set cement	retaine:	r @ 1640'.	Plug th	e Pictured	Cliffs	and F	ruitlan	d
			sx. Class "						
	Circulate 1	nole $w/9$.0 ppg mud.	Perf 2	squeeze h	oles @	702'.	Set ce	ment

retainer @ 602'. Plug Ojo Alamo top w/52 sx. Class "B" cement (61

cu.ft., 100% excess). Perf 2 squeeze holes @ 183'. Circulate 130 sx. Class "B" cement (153 cu.ft. 100% excess). Install dry hole marker. Clean and reseed location.

Regulatory Affairs