

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name MARTIN - STAMPFEL	
9. Well No. 1	
10. Field and Pool, or Wildcat UNDESIGNATED	
12. County SAN JUAN	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator EPROL & ASSOCIATES AND MARTIN OIL & GAS CO.
3. Address of Operator 4705 N. 32ND PLACE, PHOENIX, ARIZONA	4. Location of Well UNIT LETTER 0, 336 FEET FROM THE South LINE AND 1650 FEET FROM THE EAST LINE, SECTION 3 TOWNSHIP 29 N RANGE 16 W NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 5020 GR	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

This well has been Plugged & Abandoned in the following MANNER:

- 1-12-66 Move in Equipment Pre to P&A
- 1-14-66 Spotted 10 sx plug from 3400 to 3505 & Squeeze w/1200psi left Cement from 3460 to 3505. Shot 4 1/2" casing off @ 2736. Recover Same
- 1-15-66 Spot 15 sx plug from 2786 to 2686
- 1-16-66 - 1-24-66 Suspended Operations
- 1-25-66 - Shot 7" casing off @ 728 Recover Same
- 1-26-66 Spot 50 sx plug from 778 to 678
Spot 50 sx plug from 560 to 460
Erect P&A MARKER w/ 10 sx Surface Plug

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>L. Pedfor</u>	TITLE <u>Agent for Operator</u>	DATE <u>5/10/66</u>
APPROVED BY <u>George Lund</u>	TITLE <u>Sup Dist TIL</u>	DATE <u>8-14-67</u>
CONDITIONS OF APPROVAL, IF ANY:		