

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 03877

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Duff

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Crouch Mesa MV

11. SEC., T., R., M., OR BLK. AND
SUBVY OR AREA

Sec. 5, T-29-N, R-11-W
N.M.P.M.

12. COUNTY OR PARISH

San Juan

13. STATE

NM

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Meridian Oil Inc.

3. ADDRESS OF OPERATOR

Post Office Box 4289, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface 1650'S, 1090'W

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, OR, etc.)

5820'GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

09-16-87 MOL & RU. ND WH, NU BOP. Circ w/70 bbls. wtr @ 3655'. Stung into cmt. retainer, lifted up & tested tbg to 1500#, stung back in cmt. retainer. Spotted 10 sx. below retainer, displaced tbg w/15 bbls. wtr. Pull up 5', spotted 20 sx. on top of cement retainer, displaced tbg w/15 bbls. wtr. TOOH w/tbg, removed stinger. TIH w/53 stands tbg. SDFN. WOC.

09-17-87 TIH, tag cmt @ 3522'. Pull up 4', spot 10 sx. plug. TOOH to 2757', spot 10 sx. TOOH to 2199'. Spot 25 sx. TOOH to 1730', spot 10 sx plug. TOOH w/tbg. TIH w/wireline to 850'. Perf four holes. TOOH w/wireline. TIH w/tbg to 852', squeeze w/40 sx and 30 sxs spot. TOOH w/tbg. SDFN. WOC.

09-18-87 TIH w/wireline, tag cement @ 514'. POOH to 380, perf four holes. TOOH w/wireline. Circ. bradenhead with 35 bbls. wtr. Circ. 170 sx. cement to surface. Cut off wellhead. Set dry hole marker with 10 sx. Released rig.

18. I hereby certify that the foregoing is true and correct

SIGNED

Peggy Doh

TITLE Drilling Clerk

DATE

09-24-87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

John P. Kelly

*See Instructions on Reverse Side