

OH CONSERVATION COMMISSION

STATE OF NEW MEXICO 1000 RIO BRAZOS RD. - AZTEC

87410

DIRECTOR
JOE D. RAMEY

LAND COMMISSIONER
PHIL R. LUCERO

STATE GEOLOGIST EMERY C. ARNOLD

. August 9, 1976

Mr. W. D. Dawson El Paso Natural Gas Co. P. O. Box 990 Farmington, New Mexico

Re: El Paso Natural Gas Co. Oswell #1 K-3-29N-11W

Dear Mr. Dawson:

I recently stopped by the subject well and opened the casing valves slightly. There is gas on both casing strings.

Please contact Mr. Charles Gholson of this office and arrange for a witnessed Bradenhead Test.

Other wells nearby have the 3radenhead valves open without any apparent flow.

If there are questions please contact us.

Yours very trulx.

A. R. Kendrick

Supervisor, District #3

ARK:mc

xc: Oil Conservation Commission Santa Fe, New Mexico

> Mr. Charles Gholson Oil Conservation Commission Aztec, New Mexico

DISTRIBUTION SANTA FE // NEW MEXICO OIL CONSERVATION COMMISSION FILE U.S.G.S. LAND OFFICE OPERATOR	Form C-103 Supersedes Old C-102 and C-103 Effective 14-65 5a. Indic ite Type of Leane State Pee X 5, State Oil 6 Gas Leane No.
SUNDRY NOTICES AND REPORTS ON WELLS TOO NOT USE THIS LOGIC FOR PROPERTY OF THE PROPERTY OF THE PROPERTY RESERVOIR.	
I. OIL GAS X WELL OTHER-	7. Unit Aspeciment Manie
El Paso Natural Gas Company	8, Paris of Leane Name Oswell
PO Box 990, Farmington, NM 87401	s, Well Ro.
4. Location of Well K 1650 FEET FROM THE SOUTH LINE AND 1650 FEET FROM	10. Field and Pool, or Willest Aztec Pic.Cliffs
THE West LINE, SECTION 3 TOWNSHIP 29N RANGE 11W NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 5688 GR	12. County San Juan
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING CHANGE PLANS CHANGE PLANS CHANGE PLANS OTHER CUrrent Status OTHER T. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	
A second approval is requested to retain this well in its present temporarily abandoned status. It is being evaluated as a possible rework in the Pictured Cliffs formation. The most recent bradenhead test indicates there has been no change in the well's condition since it was shut-in. Periodic visits to the wellsite to check the bradenhead and surface equipment will be made until either thei well is reworked or permanently plugged and abandoned.	
	JIII O ISIN
18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNED	July 6, 1976
APPROVED BY APPROVAL, IF ANY:	