
-

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See addi-

	Indicate Nature of Notice by Ch	ecking B	low	
otice of Intention Change Plans	Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	
OTICE OF INTENTION PLUG WELL	Notice of Intention to Plug Back		Notice of Intention to Set Liner	
otice of Intention Squeeze	Notice of Intention to Acidize		Notice of Intention to Shoot (Nitro)	
otice of Intention Gun Perforate	Notice of Intention (Other) WORKOVER	x	Notice of Intention (Other)	
IL CONSERVATION COMMISS	SION Paraington, How Mex	dan .	12-1-64	
MIA PE, NEW MEXICO	(Place)		(Date)	•••••••
ntlemen:				
Following is a Notice of Intenti	ion to do certain work as described below at			
Astec Oll & One Co:	pany NCRATE		Well No3 in	J
(Company or	7 Operator) 3 , T 298 , R		Fulcher-Kutz	(Unit)
(40-acre Subdivision)			•	
Propose To:	FULL DETAILS OF PROPOSED OLLOW INSTRUCTIONS IN THE RUL			
Propose To: Pull 1" tubing, clear Run 3-1/2" casing to Farmington sones. Perforate and sand was		ES AND	regulations) possible holes in Fruit!	post of
Propose To: Pull 1" tubing, clear Run 3-1/2" casing to Famington some. Perforate and sand w Run 1" tubing and put	out to 2000 feet or TD. TD and cement to surface, so	ES AND	possible holes in Fruit! 1940 to 1975 RECEIVE	6
Propose To: Pull 1" tubing, clear Run 3-1/2" casing to Paguington mones. Perforete and sand we Run 1" tubing and put	out to 2000 feet or TD. TD and cement to surface, so	ES AND	possible holes in Fruiti 1940 to 1975 PEC 2 1964 OIL CON. CC DIST. 3	6
Propose To: Pull 1" tubing, clear Run 3-1/2" casing to Paguington mones. Perforete and sand we Run 1" tubing and put	a cut to 2000 feet of TD. TO end cement to surface, so ster free Pictured Cliffs sor t well back on production	ES AND	possible holes in Fruiti 1940 to 1975 PEC 2 1964 OIL CON. CO DIST. 3 Astec Oil & Gas Company Company or Operator Original Signer By	6
Propose To: Pull 1" tubing, clear Run 3-1/2" casing to Farmington mones. Perforate and sand we Run 1" tubing and put DEC 2 1964 pproved	a cut to 2000 feet of TD. TO end cement to surface, so ster free Pictured Cliffs sor t well back on production	ES AND	possible holes in Fruiti 1940 to 1975 PEC 2 1964 OIL CON. CC DIST. 3	6
Propose To: Pull 1" tubing, clear Run 3-1/2" casing to Parmington sonse. Perforate and sand w Run 1" tubing and put DEC 2 1964 pproved	a cut to 2000 feet or TD. TD end cement to surface, equator free Pictured Cliffs son twell back on production By	es and	possible holes in Fruiti 1940 to 1975 PEC 2 1964 OIL CON. CC DIST. 3 Astec Call & Cas Company Company or Operator Original Signed By Carl E. Jamesur	6
Propose To: Pull 1" tubing, clear Run 3-1/2" casing to Parsington sones. Perforate and send we Run 1" tubing and put DEC 2 1964 pproved scept as follows: pproved IL CONSERVATION COMMISS Uriginal Signed Wilse A. R. KENDRICK	a cut to 2000 feet of TD. TD end cement to surface, so ster free Pictured Cliffs sor t well back on production By	es and	possible holes in Fruit! 1940 to 1975 PEC 2 1964 OIL CON. CO DIST. 3 Astec Oil & Gas Company Company or Operator Original Signed Rv Carl E. Jamesur District Engineer	D.M.
Propose To: Pull 1" tubing, clear Run 3-1/2" casing to Farmington mones. Perforate and sand we Run 1" tubing and put DEC 2 1964 pproved	a cut to 2000 feet of TD. TD end cement to surface, so ster free Pictured Cliffs sor t well back on production By	es and	possible holes in Fruit! 1940 to 1975 PEC 2 1964 OIL CON. CO DIST. 3 Astec Oil & Gas Company Company or Operator Original Signed By Garl E. Jamesur District Engineer Communications regarding well to:	D DM.