(Feb. 1981)							
i							

Form 9-881a

(SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Fe				
Lease No. 078578					
Unit <u>£/2</u>	Sec. 21				

## SUNDRY NOTICES AND REPORTS ON WELLS

1862

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF KILLING TO REPAIR XX
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL.	I I
	1

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

			May 2	, 19 <u>.62</u>
Florance Well No. 40 is located	1650 ft. fro	m_//8/ line	and 1825 ft. from E lin	e of sec. 21
NE/4 Section 21	T-30-N	R-8-W	NMPM	
(1/4 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
Blanco Mesaverde	San	Juan	New Mexi	co
(Field)	(County	y or Subdivision)	(State or Terri	ory)

The elevation of the derrick floor above sea level is 5819 ft. D. F.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pumped 47 barrels 13# drilling mud down braden head. Well still had pressure on braden head. Well kicking through crater. Pumped 135 sacks 18# cement down braden head. Displaced surface casing with water. Well still kicking through crater. Pumped 200 sacks of 25% calseal cement down braden head, displacing braden head with water. Crater dead. Braden head shut-in w/pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey of ore operations may Mormenced.

Company Delhi-Taylor Gil Corporation

Address P. O. Drawer 1198

Farmington, New Sexico

By G. T. HIGGINDOTHAM

G. T. Higginbotham

Title District Superintendent