

(Form C-104)
Revised 7/1/57

Recompletion

Farmington, New Mexico **April 17, 1959**

Address Box 997, Farmington, New Mexico

WORKOVER

3-14-59 Rig up Evitt Drlg. Co. rotary rig # 4.
3-15-59 Pulled tubing. Ran Bridge Plug on wire line.
3-16-59 Testing casing for hole. Isolated casing leak between 180-210'.
Set Guiberson Mag. Bridge Plug at 4700'. Set Baker Full Bore
packer at 85'. Squeezed w/100 sacks Neat. Circulated cement
thru Braden head valve. Final sq. press. 1500#.
3-17-59 Drilling cement. Press. up on casing w/1200#. Held.
3-18-59 Drilling B.P. Blowing hole and cleaning out.
3-19-59 Blowing and cleaning hole. Twisted off 3 joints down. Went in
w/overshot. Recovered fish.
3-20-59 Blowing hole and cleaning out. Ran 182 jts. 2" tbg.(5424'), set @ 5435'.
3-30-59 Date well was tested.