Form 9-331 (May 1963)	UNITED STATES SUBMIT IN TRIPLICATE DEPARTMENT OF THE INTERIOR verse side)
(Do not	SUNDRY NOTICES AND REPORTS ON WELLS use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)
OIL WELL	Use "APPLICATION FOR PERMIT—" for such proposals.) GAS WELL X OTHER
2. NAME OF OPE	

	Form approved. Budget Bureau No. 42-R1424	١.
5. LEASE	DESIGNATION AND SERIAL NO.	

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREE OIL WELL X OTHER 2. NAME OF OPERATOR Tenneco Oil Company 3. ADDRESS OF OPERATOR P. O. Box 1714, Durango, Colorado 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1190 FSL, 1190 FEL Unit P Sec 6, T 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5942 Gr. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT X ALT	TENT NAME ASE NAME CE POOL, OR WILDCAT Pictured Cliffs M., OR BLK. AND OR AREA -30-N, R-8-W PARISH 13. STATE . New Mexico
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. OIL Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREE OIL ORATOR Tenneco Oil Company Address of Operator P. O. Box 1714, Durango, Colorado 103 Location of well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1190 FSL, 1190 FEL Unit P Sec 6, T 4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5942 Gr. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPORT OF WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPORT OF WATER SHUT-OFF FRACTURE TREAT SHOOTING OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.)*	POOL, OR WILDCAT Pictured Cliffs M., OR BLK. AND OR AREA -30-N, R-8-W PARISH 13. STATE . New Mexico
OIL WELL WELL X OTHER 7. NAME OF OPERATOR Tenneco Oil Company Address of Operator P. O. Box 1714, Durango, Colorado P. O. Box 1714, Durango, Colorado 103 Location of well (Report location clearly and in accordance with any State requirements.* At surface 1190 FSL, 1190 FEL Unit P Sec 6, T 4. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5942 Gr. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE ABANDON* CHANGE PLANS (Other) 7. DENCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and attes, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.)*	POOL, OR WILDCAT Pictured Cliffs M., OR BLK. AND OR AREA -30-N, R-8-W PARISH 13. STATE . New Mexico
NAME OF OPERATOR Tenneco Oil Company ADDRESS OF OPERATOR P. O. Box 1714, Durango, Colorado 103 Location of well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1190 FSL, 1190 FEL Unit P Sec 6, T 4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5942 Gr. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOTING OR ACIDIZE REPAIR WELL (Other) Change Plans (Other) Change Plans (Other) Change Plans (Other) Completion or Recompletion Report and proposed own. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.)*	POOL, OR WILDCAT Pictured Cliffs M., OR BLK. AND OR AREA -30-N, R-8-W PARISH 13. STATE . New Mexical AIRING WELL ERING CASING
Tenneco 0il Company ADDRESS OF OPERATOR P. O. Box 1714, Durango, Colorado Location of Well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1190 FSL, 1190 FEL Unit P Sec 6, T 4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5942 Gr. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIZE ABANDON* CHANGE PLANS (Other) (Other) Completion or Recompletion Report and Proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.)* 2866 PETD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	POOL, OR WILDCAT Pictured Cliffs M., OR BLK. AND OR AREA -30-N, R-8-W PARISH 13. STATE . New Mexical AIRING WELL ERING CASING
ADDRESS OF OPERATOR P. O. Box 1714, Durango, Colorado 103 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1190 FSL, 1190 FEL Unit P Sec 6, T FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5942 Gr. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) CHANGE PLANS (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated to this work.)* 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	POOL, OR WILDCAT Pictured Cliffs M. OR BLK. AND OR AREA -30-N, R-8-W PARISH 13. STATE . New Mexic
P. O. Box 1714, Durango, Colorado LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* At surface 1190 FSL, 1190 FEL Unit P Sec 6, T FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) THEST WATER SHUT-OFF FRACTURE TREAT MULTIPLE COMPLETE MULTIPLE COMPLETE FRACTURE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE REPAIR WELL (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.)* 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	Pictured Cliffs M., OR BLE. AND OR ABEA -30-N, R-8-W PARISH 13. STATE New Mexic AIRING WELL ERING CASING
DOCATION OF WELL (Report location clearly and in accordance with any State requirements.* 10. FIELD AND Blanco 1190 FSL, 1190 FEL Unit P Sec 6, T Survey Sec 6, T 12. COUNTY OF Sec 6, T Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.)* 10. FIELD AND Blanco 11. SEC. T. R. SUBVEY Sec 6, T 12. COUNTY OF San Juan WATER SHUT-OFF FRACTURE TREATMENT X ALT SHOOT OR ACIDIZE (Other) (Note: Report results of multiple con (Note) (Note: Report results of multiple con completion or Recompletion Report and nent to this work.)* 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	Pictured Cliffs M., OR BLE. AND OR ABEA -30-N, R-8-W PARISH 13. STATE New Mexic AIRING WELL ERING CASING
Blanco 1190 FSL, 1190 FEL Unit P Sec 6, T FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5942 Gr. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.)* 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	M, OR BLE. AND OR AREA -30-N, R-8-W PARISH 13. STATE . New Mexic AIRING WELL ERING CASING
Unit P Sec 6, T FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.) 5942 Gr. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.)* 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	M, OR BLE. AND OR AREA -30-N, R-8-W PARISH 13. STATE . New Mexic AIRING WELL ERING CASING
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.) 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	-30-N, R-8-W PARISH 13. STATE New Mexic AIRING WELL ERING CASING
TEST WATER SHUT-OFF PULL OR ALTER CASING NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	PARISH 13. STATE New Mexic AIRING WELL ERING CASING
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE REPAIR WELL (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.) 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	New Mexic
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.) 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	AIRING WELL
NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PULL OR ALTER CASING MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON* (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.)* 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	AIRING WELL
PULL OR ALTER CASING FRACTURE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.) 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	AIRING WELL
FRACTURE TREAT SHOOT OR ACIDIZE ABANDON* CHANGE PLANS (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.) 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	ERING CASING
FRACTURE TREAT SHOOT OR ACIDIZE ABANDON* CHANGE PLANS (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.) 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	ERING CASING
CHANGE PLANS (Other) (Other) (Note: Report results of multiple con Completion or Recompletion Report and Completion or Recompletion Report and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.) 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	VDONMENT*
(Other) (Note: Report results of multiple completion or Recompletion Report and Completion or Recompletion Report and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.)* 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	1 1
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estim proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all nent to this work.) 2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	
2866 PBTD. 10/18. Ran correlation log and CBL. Perf 2749-52, 2756-58, 69, 2771-73 2789-91, 2798-2800 w/24 holes. Frac w/30,000# sd	Log form.)
ි දැන්නත් යුතු විශ්ය විශ්ය විශ්ය විශ්ය වි	그런 열충된.
- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
	ရည်သို့ ရှိ ကြိန်သာမှ
	EIVEL
	L 3 1957
	GICAL SURVEY
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
I hereby certify that the foregoing is true and correct	
SIGNED TITLE DATE	
M, K, Wagner (This space for Federal or State office use)	11/8/67
	11/8/67
APPROVED BY DATE	11/8/67
	11/8/67
USGS (5) 7	11/8/67
*See Instructions on Reverse Side	11/8/67