	į – į
Form 3160-5 UNITED STATES	FORM APPROVED
(June 1990) DEPARTMENT OF THE INTERIOR	Budget Bureau No. 1004-0135
porture of the second	/ Expires: March 31, 1993
BUREAU OF LAND MANAGEMENT	5. Lease Designation and Serial No.
	NM 10758
SUNDRY NOTICES AND REPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to drill or to deepen or reentry to a different reserve	volr.
Use "APPLICATION FOR PERMIT—" for such proposals	
	7. If Unit or CA, Agreement Designation
SUBMIT IN TRIPLICATE	7
1. Type of Well	A 30 4 50 4 50 4 50 4 50 4 50 4 50 4 50 4
Oil Gas Other P&A	8. Well Name and No.
2. Name of Operator	Pittam Pond #4
Dugan Production Corp.	9. API Well No.
3. Address and Telephone No.	30-045-25176
P.O. Box 420, Farmington, NM 87499 (505) 325-1821	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Cha Cha Gallup
4. Location of Well (Poolage, Sec., I., R., M., or Survey Description)	11. County or Parish, State
690' FSL & 690' FWL	
Sec. 1, T29N, R15W	San Juan, NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, RE	EPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACT	TION
	Change of Plans
Notice of Intent Notice of Intent Recompletion	New Construction
Subsequent Report Plugging Back	Non-Routine Fracturing
Casing Repair	Water Shut-Off
Final Abandonment Notice Altering Casing	Conversion to Injection
Other	Dispose Water
	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of	
Plugged well as follows: 1. Load hole with mud. 2. Spot 24 cu. ft. class "B" cement from 4140-3 hours. T.I.H. Tag cement top @ 4242*. 3. T.O.H. to 4190'. Spot 18 cu. ft. plug 4190-4. T.O.H. to 2180'. Spot 18 cu. ft. plug 2180-5. T.O.H. to 540'. Est. rate down bradenhead. Spot 35 cu. ft. plug 540-140'. 6. T.O.H. with tubing. Pump 67 cu. ft. down br 7. Fill 4½" casing 50' - to surface. 8. Cut off casing and set dry hole marker. Job 92. Approved as to plugging of the well bore Liability under bond is retained until surface restoration is completed.	4090'. 2030'. 3 BPM @ 300 psi. radenhead. FA BCCE
 Load hole with mud. Spot 24 cu. ft. class "B" cement from 4140-3 hours. T.I.H. Tag cement top @ 4242". T.O.H. to 4190'. Spot 18 cu. ft. plug 4190-4. T.O.H. to 2180'. Spot 18 cu. ft. plug 2180-5. T.O.H. to 540'. Est. rate down bradenhead. Spot 35 cu. ft. plug 540-140'. T.O.H. with tubing. Pump 67 cu. ft. down br 7. Fill 4½" casing 50' - to surface. Cut off casing and set dry hole marker. Job 92. Approved as to plugging of the well bore Liability under bond is retained until	4090'. 2030'. 3 BPM @ 300 psi. radenhead. FABSTER BLANCE OF THE BLANCE O
1. Load hole with mud. 2. Spot 24 cu. ft. class "B" cement from 4140-3 hours. T.I.H. Tag cement top @ 4242'. 3. T.O.H. to 4190'. Spot 18 cu. ft. plug 4190-4. T.O.H. to 2180'. Spot 18 cu. ft. plug 2180-5. T.O.H. to 540'. Est. rate down bradenhead. Spot 35 cu. ft. plug 540-140'. 6. T.O.H. with tubing. Pump 67 cu. ft. down br 7. Fill 4½" casing 50' - to surface. 8. Cut off casing and set dry hole marker. Job 92. Approved as to plugging of the well bore Liability under bond is retained until surface restoration is completed.	4090'. 2030'. 3 BPM @ 300 psi. radenhead. 92 complete 8-17.
1. Load hole with mud. 2. Spot 24 cu. ft. class "B" cement from 4140-3 hours. T.I.H. Tag cement top @ 42424. 3. T.O.H. to 4190'. Spot 18 cu. ft. plug 4190-4. T.O.H. to 2180'. Spot 18 cu. ft. plug 2180-5. T.O.H. to 540'. Est. rate down bradenhead. Spot 35 cu. ft. plug 540-140'. 6. T.O.H. with tubing. Pump 67 cu. ft. down br 7. Fill 4½" casing 50' - to surface. 8. Cut off casing and set dry hole marker. Job 92. Approved as to plugging of the well bore Liability under bond is retained until surface restoration is completed. 14. I hereby certify that the foregoing if true and correct Signed Tide Operations Manager	2030'. 3 BPM @ 300 psi. radenhead. FA BLYE Complete 8-172 BLYE NA H. STON. N. M. STON. N.
1. Load hole with mud. 2. Spot 24 cu. ft. class "B" cement from 4140-3 hours. T.I.H. Tag cement top @ 4242". 3. T.O.H. to 4190'. Spot 18 cu. ft. plug 4190-4. T.O.H. to 2180'. Spot 18 cu. ft. plug 2180-5. T.O.H. to 540'. Est. rate down bradenhead. Spot 35 cu. ft. plug 540-140'. 6. T.O.H. with tubing. Pump 67 cu. ft. down br 7. Fill 4½" casing 50' - to surface. 8. Cut off casing and set dry hole marker. Job 92. Approved as to plugging of the well bore Liability under bond is retained until surface restoration is completed. 14. I hereby certify that the force only is frue and correct Signed On John Alexander Tide Operations Manager Tide Operations Manager	4090'. 2030'. 3 BPM @ 300 psi. radenhead. FARSTON. RECEIVED BLM BLM 8/10/02
1. Load hole with mud. 2. Spot 24 cu. ft. class "B" cement from 4140-3 hours. T.I.H. Tag cement top @ 4242". 3. T.O.H. to 4190'. Spot 18 cu. ft. plug 4190-4. T.O.H. to 2180'. Spot 18 cu. ft. plug 2180-5. T.O.H. to 540'. Est. rate down bradenhead. Spot 35 cu. ft. plug 540-140'. 6. T.O.H. with tubing. Pump 67 cu. ft. down br. 7. Fill 4½" casing 50' - to surface. 8. Cut off casing and set dry hole marker. Job 92. Approved as to plugging of the well bore Liability under bond is retained until surface restoration is completed. 14. I hereby certify that the foresoft is free and correct Signed Johns Alexander Tide Operations Manager Tide Operations Manager	A PPROVED
1. Load hole with mud. 2. Spot 24 cu. ft. class "B" cement from 4140-3 hours. T.I.H. Tag cement top @ 4242". 3. T.O.H. to 4190'. Spot 18 cu. ft. plug 4190-4. T.O.H. to 2180'. Spot 18 cu. ft. plug 2180-5. T.O.H. to 540'. Est. rate down bradenhead. Spot 35 cu. ft. plug 540-140'. 6. T.O.H. with tubing. Pump 67 cu. ft. down br 7. Fill 4½" casing 50' - to surface. 8. Cut off casing and set dry hole marker. Job 92. Approved as to plugging of the well bore Liability under bond is retained until surface restoration is completed. 14. Thereby certify that the foregoing is frue and correct Signed Operations Manager Tide Operations Manager	2030'. 3 BPM @ 300 psi. radenhead. FABLE BLM Complete 8-172 BLM Date 8/19/92
1. Load hole with mud. 2. Spot 24 cu. ft. class "B" cement from 4140-3 hours. T.I.H. Tag cement top @ 4242". 3. T.O.H. to 4190'. Spot 18 cu. ft. plug 4190-4. T.O.H. to 2180'. Spot 18 cu. ft. plug 2180-5. T.O.H. to 540'. Est. rate down bradenhead. Spot 35 cu. ft. plug 540-140'. 6. T.O.H. with tubing. Pump 67 cu. ft. down br. 7. Fill 4½" casing 50' - to surface. 8. Cut off casing and set dry hole marker. Job 92. Approved as to plugging of the well bore Liability under bond is retained until surface restoration is completed. 14. I hereby certify that the foresoft is free and correct Signed Johns Alexander Tide Operations Manager Tide Operations Manager	2030'. 3 BPM @ 300 psi. cadenhead. 92 ABEA MANAGER

*See Instruction on Reverse Side