

Date Remediation Started: N/A Date Completed: _____

Excavation _____ Approx. cubic yards _____

Landfarmed _____ Insitu Bioremediation _____

Other _____

Remediation Method: Onsite _____ Offsite _____
(Check all appropriate sections)

General Description of Remedial Action: N/A

Because of sandstone and bedrock the initial assessment at 1' below pit bottom
showed soils to be clean at the both the surface and 1' below the pit bottom.

Ground Water Encountered: No X Yes _____ Depth _____

Final Pit: Sample location deepest part of pit. Sampled with a backhoe.

Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

Sample depth 1' below pit bottom

Sample date 9/7/93 Sample time _____

Sample Results

Benzene (ppm) _____

Total BTEX (PPM) _____

Field Headspace (ppm) 17.1

TPH 760

Ground Water Sample: Yes _____ No X (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETED TO THE BEST
OF MY KNOWLEDGE AND BELIEF.

DATE 8/18/94 PRINTED NAME Ed Hasely

SIGNATURE  and TITLE Environmental Engineer

REVISED DATE: SEPTEMBER 09, 1993

HEO

PIT NO.	WELL NAME	U S T R	PIT TYPE	RANK SCORE	CLOSURE STANDARD TPH (PPM)	DATE 1993	GROUNDWATER MONITORED Sub-Surf. Depth	SOIL TYPE	PIT TYPE	SAMPLE NO.	Organic Vapor Matter (PPM)	Total Recoverable		EPA METHOD 8020 (PPB)				TOTAL BTEX	STATUS
												Peric. Hydro. (PPM)	Benzene	Toluene	Ethyl Benzene	Xylene			
PA056	SAN JUAN 29-6, #9	M302906	SEP	10	1000	9-03	NO	OL	EARTHEN	T1-4.5	0	0	0						CLOSE
PA057	SAN JUAN 29-6, #25	B322906	SEP	10	1000	9-03	NO	SM	EARTHEN	T1-4	718	100	15.3	97	23.3	272	407.6	CLOSE	
PA058	SAN JUAN 29-6, #55A	C182906	SEP	20	100	9-03	NO	SM	EARTHEN	T1-6	685	1800						REM	
										T1-11	555	2000							
										T1-14	512	3300							
										T2-5	0								
										T2-10	43	10							
										T2-15	629	1600							
PA059	SAN JUAN 30-5, #95 DK	H283005	SEP	10	1000	9-07	NO	CL	EARTHEN	T1-4.5	195	0						REM ?	
										T1-7	87								
PA060	SAN JUAN 31-6, #37 DK	P363106	SEP	0	5000	9-07	NO	SM	EARTHEN	T1-4	50	4400						CLOSE	
PA061	SAN JUAN 31-6, #42 DK	A363106	SEP	0	5000	9-07	NO	SP	EARTHEN	T1-2.5	17.1	760						CLOSE	
PA062	SAN JUAN 31-6, #38 DK	C023006	SEP	0	5000	9-07	NO	CL	EARTHEN	T1-5.5	1.6	34						CLOSE	
										T1-8	24								
PA063	SAN JUAN 31-6, #48 DK	P023006	SEP	0	5000	9-07	NO	CL	EARTHEN	T1-4	23	0						CLOSE	
										T1-6.5	23								
PA064	SAN JUAN 31-6, #46	A323106	SEP	20	100	9-08	NO	CL	EARTHEN	T1-6.5	10	0						CLOSE	
										T1-9	0								
PA065	SAN JUAN 31-6, #47 DK	L323106	SEP	0	5000	9-08	NO	CL	EARTHEN	T1-5	20	12						CLOSE	
										T1-7.5	53								
PA066	SAN JUAN 29-6, #15-2	K022906	SEP	10	1000	9-08	NO	CL	EARTHEN	T1-4.5	5	110	42.9	580	328	7570	8520.9	CLOSE	
										T1-7	905								
PA067	SAN JUAN 29-6, #37-16	A162906	SEP	10	1000	9-08	NO	CL	EARTHEN	T1-4.5	707	44	16.4	710	24.6	498	1249	REM ?	
										T1-7	817								

