

COPIES OF THIS REPORT RECEIVED	3
DISTRIBUTION	
DATE	1
FILE	1
CLASS.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-11479-22	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. SEE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. Indicate Type of Well OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Public Petroleum Corporation		8. Farm or Lease Name Delhi State <i>Com</i>
3. Address of Operator Post Office Box 869, Albuquerque, New Mexico 87103		9. Well No. #1
4. Location of Well UNIT LETTER <u>I</u> , <u>1800</u> FEET FROM THE <u>south</u> LINE AND <u>890</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>30N</u> RANGE <u>9W</u> NMPM.		10. Field and Pool, or Wildcat Blanco Pictured Cliffs
15. Elevation (Show whether DF, RT, GR, etc.) 5847 Gr.		12. County San Juan

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was damaged by fresh water from a casing leak at 1,063'.  
It is proposed to plug and abandon the well as follows:

1. Squeeze perforations at 2524-46' with 50 sacks. Class C neat.
2. Set 50 sx. plug in 4-1/2" casing from 1200' to 500'.
3. Squeeze 25 sx. through hole in casing at 1063'.
4. Squeeze Bradenhead with 25 sx. Class C neat.
5. Set dry hole marker at surface.

NOTE: No casing recovery will be attempted.

Verbal approval was obtained from Mr. Emory Arnold on December 30, 1968.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Donald C. Walker</u> D. C. Walker	TITLE <u>District Engineer</u>	DATE <u>January 2, 1969</u>
APPROVED BY <u>Emory Arnold</u>	TITLE <u>Sup Dist III</u>	DATE <u>1-6-69</u>
CONDITIONS OF APPROVAL, IF ANY:		