

*Should have been done on a yellow card. This is a fee well.
 Yellow card is in Kander file drawer. 9-6-89*

F. Loc. 1650/N; 1650/E Elev. 5610 Spd. 9-15-44 Comp. 9-15-45 TD. 1808 PB.

Casing S. 12 1/2 @ 40 W. 12 Sx. Int. @ W. Sx. Pr. 7 @ 1700 W. 50 Sx. T. @
 Csg. Perf. Prod. Stim.

T
R
A
N
S

I.P. 2250 MCF/D After Hrs. SICP PSI After Days GOR Grav. 1st Del. s

TOPS		NITD	Well Log	TEST DATA						
Kittland OIS	259	C-103	Plot	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland	1150	C-104	Electric Log	4/16/66	207	11	108	166	6	
Pictured Cliffs	699		C-122	disconnected 4-16-69						
Cliff House		Ditr	Dfa							#1520
Menefee		Datr	Dac							
Point Lookout		/Redfern & Herd. /MSBW /Redfern Dev. Corp. NIT- P+ A 5-6-82 Reamut to past pine P+ A 7-1-82 in title after 5-1-82								
Mancos										
Gallup										
Sanostee										
Greenhorn										
Dakota										
Morrison										
Entrada		/Fing-Redfern O. Co.								
			160							

o Ful-Kutz PC Co. SJ S 23 T 30N R 12W U G Oper. Kerr-McGee Corp. Lse. Hargis No.