

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

SF 073139

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Elliott Gas Com "F"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Blanco Mesaverte

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

NE/4 NE/4 Section 33,  
T-30-N, R-9-W

12. COUNTY OR PARISH

San Juan

18. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☐ GAS ☒  
WELL WELL OTHER

2. NAME OF OPERATOR  
AROCO PRODUCTION COMPANY

3. ADDRESS OF OPERATOR  
501 Airport Drive, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

990' FNL & 990' FEL, Section 33, T-30-N, R-9-W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GL 5765', DF 5775'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*


In May, 1975, casing repair was attempted when 1700' tubing dropped in hole, and could not be recovered, so the well was plugged and abandoned on October 14, 1975 as follows:

1. Pulled 2-3/8" tubing and loaded hole with water.
2. Set Model "K" cement retainer at 3100' in 5" casing and could not pump past fish.
3. Stung out of retainer and pumped 50 sacks Class "B" Neat cement on top of retainer.
4. Spotted 30' cement plug in top of hole.
5. Erected P&A marker and cleaned up location.

RECEIVED

OCT 17 1975

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.



18. I hereby certify that the foregoing is true and correct

SIGNED

*[Signature]*

TITLE Area Engineer

DATE October 16, 1975

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side