

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR AMOCO PRODUCTION COMPANY	8. FARM OR LEASE NAME Elliott Gas Com "F"
3. ADDRESS OF OPERATOR 501 Airport Drive, Farmington, New Mexico 87401	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FNL & 990' FEL, Section 33, T-30-N, R-9-W	10. FIELD AND POOL, OR WILDCAT Blanco Mesaverde
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA NE/4 NE/4 Section 33, T-30-N, R-9-W
15. ELEVATIONS (Show whether DF, RT, GR, etc.) GL 5765', DF 5775'	12. COUNTY OR PARISH San Juan
	13. STATE New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

In May, 1975, casing repair was attempted when 1700' tubing dropped in hole, and could not be recovered, so the well was plugged and abandoned on October 14, 1975 as follows:

1. Pulled 2-3/8" tubing and loaded hole with water.
2. Set Model "K" cement retainer at 3100' in 5" casing and could not pump past fish.
3. Stung out of retainer and pumped 50 sacks Class "B" Neat cement on top of retainer.
4. Spotted 30' cement plug in top of hole.
5. Erected P&A marker and cleaned up location.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Area Engineer


(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE



DATE October 16, 1975

\*See Instructions on Reverse Side

AMOCO