

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 012150
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


_____ October 23 _____, 19 61
Federal "FC"
Well No. 1-31 is located 790 ft. from N line and 1820 ft. from W line of sec. 31
NELSON Sec. 31 34N 11W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5822 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

October 3, 1961 - Discussed plugging procedure with Mr. Rudy Bear. We plan to squeeze Picture Cliff formation with 30 sacks regular neat cement. Remove all five 3 1/2" casing. Set 30' plug in stub of casing and 50' plug on top of casing stub. Set 160' plug from 800' to 700'. Set 10 sack surface plug and put up marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company John H. Trigg
Address P. O. Box 120
Hogwell, New Mexico

By John H. Trigg
Title Owner