


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency .....

Allottee .....

Lease No. 14-00-603-1015



## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<b>RECEIVED</b> AUG 29 1963 U. S. GEOLOGICAL SURVEY FARMINGTON, NEW MEXICO
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Location \_\_\_\_\_ August 23, 1963

Well No. 2 is located 500 ft. from [N] line and 300 ft. from [E] line of sec. 34

N 1/4 34 30N 10E RYON

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Indian Lake San Juan Co., New Mexico

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5150 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

FEB 7 1964

Installed 1/2 inch pump.

Proposed to pull casing, pull casing, and cementing

from 15 to surface. To set hole marker, check hole and  
clean bottom.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Marshall Budd  
Address 1615 Camino Rio  
Farmington, New MexicoBy Marshall Budd

Title \_\_\_\_\_