

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1900, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 E. Spruce Rd., Aztec, NM 87410

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL WELL ☐

GAS WELL ☒

OTHER

2. Name of Operator

Norman L. Gilbreath

3. Address of Operator

P.O. Box 208

7. Lease Name or Unit Agreement Name

MONTANO

8. Well No.

1

9. Pool name or Wildcat

Fulcher Kutz P.C.

4. Well Location

Unit Letter B : 1650 Feet From The West Line and 330 Feet From The South Line

Section 28

Township 30N

Range 12W

NMPM

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

OIL CON

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-4-93--Petra Co rigged up ,pulled 57 jts 3/4" rods and pump
pulled 50 jts 2 3/8" tubing,inspected tubing. TIH 50 jts tagged up .Western spotted
with 26 sacs cement. TOOH shut down.

1-5-93--TIH and tag plug 5 jts out ,lay down 28 jts ,11 stds in derrick .Rig up Blue
Jet, shot 2' holes 850' ,TIH 23 jts, packer breakdown holes,TOOH packer TIH retainer
pump plug .Rig down 12 jts, 5 stds TIH packer 7 jts , isolate hole 175' . Lay down
all but 1 jt ,set packer circulate cement to surface . Rig down.

1-6-93--- Cementers,Inc. used 55 sacks of cement.Run 45' 1" beside csg. pump to,
surface, pull pipe. Run 1" pipe down csg. pump cement to surface. Rig to yard.

Set dry hole marker, covered pit and restored location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Norman L. Gilbreath

TITLE operator

DATE 6-28-1993

TYPE OR PRINT NAME

NORMAN L. GILBREATH

TELEPHONE NO. 632-8845

(This space for State Use)

Original Signed by CHARLES GHOLSON

DEPUTY OIL & GAS INSPECTOR, DIST. #3

APPROVED BY

TITLE

DATE JUN 28 1993

CONDITIONS OF APPROVAL, IF ANY: