STATE OF NEW MEXICO



ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

March 4, 1982

Mr. Perry Pearce Oil Conservation Division P. O. Box 2088 Santa Fe, NM 87501

Re: Forced plugging cases

Dear Perry,

Please docket the following cases:

- A case to allow A. H. Bernstein and other interested parties to appear and show cause why the Allan #1 located in F-23-29N-13W should not be reentered and plugged in accordance with a division approved plugging program.
- 2. A case to allow F. B. Umbarger, Trustee, and other interested parties to appear and show cause why the Davis Pooled Unit #1 located in I-27-29N-11W should not be reentered and plugged in accordance with a division approved plugging program.
- 3. A case to allow Francis L. Harvey and other interested parties to appear and show cause why the Pinkstaff Estate #1 located in A-29-29N-10W should not be reentered and plugged in accordance with a division approved plugging program.
- 4. A case to allow B.M.N.S. Company, American Employers Insurance, and other interested parties to appear and show cause why the Waggoner #1 located in K-29-30N-12W, the Brown #2 located in M-29-30N-12W, and the Wyper #2 located in 0-29-30N-12W should not be plugged in accordance with a division approved plugging program.

Mr. Perry Pearce March 4, 1982 Page two

- 5. A case to allow Pauly-Anderson-Pritchard and other interested parties to appear and show cause why the Maloy #1 should not be plugged in accordance with a division approved plugging program.
- 6. A case to allow E. J. Miley and other interested parties to appear and show cause why the Hare (Ransom) #1 should not be plugged in accordance with a division approved plugging program.
- 7. A case calling Benson-Montin-Greer Drilling Corporation, Hartford Accident and Indemnity Company, and other interested parties to appear and show cause why the Dustin #1 located in K-6-29N-12W, the Segal #1 located in K-10-31N-13W, the Price #1 located in N-15-31N-13W, and the Gallegos Canyon Unit #2 located in K-35-29N-12W should not be plugged in accordance with a division approved plugging program.
- 8. A case to allow Calvin Petroleum Corporation to appear and show cause why the Kaempf SWD #1 located in N-19-30N-11W should not be plugged in accordance with a division approved plugging program, and why the operator should not be found in violation of Rule 101 and fined accordingly.

Yours truly,

Frank T. Chavez District Supervisor

FTC:gc