## HINITED STATES

DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY		(Other instructions on reverse side)	5. LEASE DESIGNATION AND SERIAL NO.  SF 078977  6. IF INDIAN, ALLOTTEL OR TRIBE NAME
	CES AND REPORTS ON		
OIL GAS OTHER		KEPLIAED	7. UNIT AGREEMENT NAME
NAME OF OPERATOR		MAR 1 5 1972	8. FARM OR LEASE NAME
El Paso Natural Gas Company		MAK TO 1012	LaPlata
ADDRESS OF OPERATOR		OIL CON. COM.	9. WELL NO. 1 (P&A)
PO Box 990, Farmington, NM 87401  L LOCATION OF WELL (Report location clearly and in accordance with any State requirements.).			10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface			Basin Dakota
910'S, 905'W			11. SEC., T., R., M., OR ELK. AND SURVEY OR AREA
			Sec. 29, T-30-N, R-13-W NMPM
14. PERMIT NO.   15. ELEVATIONS (Show whether DF, RT, CR, etc.)		Gr, etc.)	12. COUNTY OR PARISH 13. STATE
		5455'GL	San Juan New Mexico
8. Check Ap	propriate Box To Indicate Nat	ure of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO:		SUBSEQ	UENT REPORT OF:
TEST WATER SHUT-OFF	CLL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	IULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	HANGE PLANS	(Other)	S and the last of
(Other)		Completion or Recomp	s of multiple completion on Well pletion Report and Log form.)
7. DESCRIBE PROPOSED OR COMPLETED OPER proposed work. If well is direction	RATIONS (Clearly state all pertinent d nally drilled, give subsurface location	letails, and give pertinent dates as and measured and true vertic	s, including estimated date of starting any cal depths for all markers and zones perti-

nent to this work.) \*

Due to a casing leak and non-production, it is planned to plug and abandon this well in the following manner:

Spot a 50 sk. cement plug to cover Dakota perforations (5820-6011').

Perforate sugeeze hole opposite the Mesa Verde and spot 50 sks. cement at hole and pressure displace 30 sks. through hole

Shoot off 4 1/2" casing at free point and spot a 75 sks. cement plug on casing stub (plug to cover the Pictured Cliffs).

Spot a 25 sk. cement plug at the base of the surface pipe.

Spot a 15 sk. cement plug at the surface with a Plug & Abandoned marker, clean location.

18. I hereby certify that the foregoing is true and correct		
SIGNED Original Signed F. H. WOOD	TITLE Petroleum Engineer	DATEMarch 14, 1972
(This space for Federal or State office use)		RECEIVED
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	MAR 1 4 1972
*Se	ee Instructions on Reverse Side	U. S. GEOLOGICAL SURVEY FARMINGTON, N. M.