

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1678 • FARMINGTON, NM 87406
505-325-2827 • FAX (505) 325-1211

11440

Rig No. NHDate Tue 3-14-95Well No. Paul Baker #1 Location _____ Company Shawco Inc.

FROM	TO	DESCRIPTION OF OPERATION
6:00	9:00	Hold safety meeting. Add bag safety to work log sheet.
9:00	10:00	Open well up. Start to cement. Add bag safety to work log sheet.
10:00		Circulate hole. Check with 64 OCH water. Circulate.
11:00		NO BAG HEAVY. Drilling into out. Try to break the plug.
11:00	11:00	Could not break TBG. Stop.
11:00		Rig up cable line. Tie with wire line & 1.395" cable.
12:00		Cut TBG @ 5,232'. Pool with wire line.
12:00	12:30	Run on TBG & work in place.
12:30		Pool having down 100' in TBG. Pull out with 1512' TBG &
2:00		10' cut off piece. Change out for 2 1/2" TBG.
3:00		Rig up wire line. Tie with wire line & 4 1/2" rubber line.
		Could not get rubber line past 3,680'. Work square ring up 90.
3:00		Pool with wire line.
3:00	3:30	Start on 4 1/2" C&B scraper & change to 1 1/2" RAMPS.
3:30		Single & TALLY 2 1/2" TBG in the hole with 4 1/2" C&B.
5:00		Scraper to 5,191'. Drain pump truck. Shut well in.
		SHUT DOWN
		(11 1/2 hrs)

Fuel & Motor Oil _____ Water Hauled 1-LOAD - A-Plus
 Rental Equipment 1-1 1/2" steel release Cement Retainer _____
 Cementing _____
 Wireline 1-1.395" cable

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Robert Whiteley	25	22,740.5	
Operator	Mike Hasing	13	118,034.4	11 1/2
Helper	BARRY Diekmann			11 1/2
Helper	mel SALAZAR			11 1/2
Helper	Lewis HALL			11 1/2

Date 3-14-95

NCI 010010A

RECEIVED
 MAR 15 1995
 OIL CON. DIV.
 DIST. 3