

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER -	7. Unit Agreement Name
2. Name of Operator Tenneco Oil Company	8. Farm or Lease Name R. L. Jackson
3. Address of Operator P. O. Box 3249, Englewood, CO 80155	9. Well No. 2
4. Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>30N</u> RANGE <u>11W</u> NMPM.	10. Field and Pool, or Wildcat Aztec P.C.
15. Elevation (Show whether DF, RT, GR, etc.)	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/19/82 - MIRUSU. Mix gel in mud pit.

1/20/82 - Finished mixing mud and installed BOP. Pld dry hole marker in two. Ran overshot mill w/basket inside and DO 3'. Pld out w/rest of dry hole marker. Picked up 1 drill collar and 7-7/8" bits and drld 20'.

1/21/82 - Drld fr 20' to 32', top plug. 2nd plug @ 137'. Mixed weight material in mud. DO rags and paper sacks to 225'. Drld cmt fr 225' to 245'. Circ'd hole clean & pld up 120'.

1/22/82 - Lay down drill collars & 7-7/8" bit. RIH w/2-3/8" tbg and 3-7/8" bit. DO fr 245' to 735'. Getting rags and shale back. Went thru bridge @ 735'. Had gas kick and line plugged. Unplugged line and circ'd until well stopped kicking. Pld up to surface.

1/25/82 - Mix gel and RIH w/tbg and bit to 1420'. Hit fill. DO to 1645'. Cmt fr 1645' to surface w/700 sx Cl-B neat cmt. POOH laying dn tbg. RDMOSU.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Denise Wilson TITLE Production Analyst DATE 4/26/82

Original Signed by FRANK T. CHAVEZ

SUPERVISOR DISTRICT 2

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE APR 27 1982

CONDITIONS OF APPROVAL, IF ANY: