

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5b. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>	7. Unit Agreement Name
. Name of Operator Southland Royalty Company			8. Farm or Lease Name McCarty
. Address of Operator PO Box 4289, Farmington, NM 87499			9. Well No. 1
. Location of well UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>30N</u> RANGE <u>12W</u> N.M.P.M.			10. Field and Pool, or Wildcat Fulcher Kutz PC
15. Elevation (Show whether DF, RT, GR, etc.)			12. County San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-20-87 MOL&RU. Killed well. ND WH. Install BOP. TOOH w/1" tbg, TIH w/1 1/4" work string to 1446'. SDFN.

10-21-87 TIH to 1658'. Tag fill. PU to 1646'. Pump 5 bbls. wtr, 16 bbls. 9# mud. Spot 10 sx. cmt. plug. Displace tbg w/3.5 bbls. wtr. TOOH w/1 1/4" tbg. WOC. TIH w/wireline. Tag plug @ 1518'. Came back up to 1370', shot 4 holes. TIH w/tbg to 1378'. Circ. hole. SI for squeeze. Would not take water. TOOH w/tbg. TIH to 1320' & shot 4 holes. SI for squeeze. Would not take water. Spot 20 sx. plug. TOOH w/1 1/4" tbg. WOC. SDFN.

10-22-87 TIH w/wireline & tag cmt. @ 1098'. Came up to 288' & shot 4 holes, circ. to surface. Pump 20 bbls. 9.2# mud ahead of cement. Spot 410 sx. cement, circ. to surf. 10 sx. cement to set dry hole marker. Released rig.

3. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jerry Cook</u>	TITLE <u>Drilling Clerk</u>	DATE <u>12-1-87</u>
Original Signed by CHARLES GHOLSON		
APPROVED BY _____	TITLE <u>DEPUTY COMMISSIONER</u>	DATE <u>DEC 03 1987</u>
CONDITIONS OF APPROVAL, IF ANY:		