Form approved. Budget Bureau No. 1004-0135 UNITED STATES

BUBMIT IN TRIPLICATE*

(Other instructions on reverse side) Form 3160-5 Expires August 31, 1985 November 1983) 5. LEASE DESIGNATION AND SERIAL NO. Formerly 9-331) BUREAU OF LAND MANAGEMENT SF-078195 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such appossis.) 7. UNIT AGREEMENT NAME WELL Y WELL OTHER S PARM OR LEASE NAME 2. NAME OF OPERATOR <u>Sellers LS</u> Tenneco Oil Company ADDRESS OF OPERATOR BUREAU OF LAND MANAGEMENT O. Box 3249, Englewood, CO 80155 FARMINGTON RESC.

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface FARMINGTON RESCURES AREA 10. PIBLD AND POOL, OR WILDCAT <u>Aztec PC</u> 11. SBC., T., B., M., OR BLK. AND SURVEY OR AREA 1650' FNL, 990' FWL Sec. 30. T30N R10W 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. NM 6109' GL <u>San Juan</u> Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. SUBSEQUENT EMPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL PULL OR ALTER CASING WATER SHUT-OFF TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREATMENT MULTIPLE COMPLETE PRACTURE TREAT ABANDONMENT⁴ SHOOTING OR ACIDIZING ABANDON* SHOOT OR ACIDIZE (Other) Production Liner CHANGE PLANS REPAIR WELL (Norz: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and gones perti-9/27/85 MIRUSU. Blow well dn. Kill well w/25 bbls 2% KCl wtr. NU 5-1/2" Larkin csghead & 6 " flange. 9/28/85 Tag fill @ 2591'. Start drilling new hole. Returns show metal cuttings. Drilling very slow. Feels like bit spudding on junk in hole. Drill 15' in 3-1/2 hrs. Circ hole clean. POOH w/bit. Teeth on bit worn. Confirm junk in hole. PU 3-1/2" 9.2# NUE 10V csg. Csg landed @ 2610'. NU cementers. Pmp 5 bbl mud. Flush followed by 40 sxs RFC cmt w/10#/sx Gilsonite & 3% CaCl2. (Bump plug to 1500 psi.) Yield 1.63 ft3/sx @ 14.6 ppg. Strip off BOP. Cut 3-1/2" & weld on wellhead. 9/29/85 RIH w/temp survey. TOC @ 1800'. 9/30/85 NUBOP. RU bluejet & RIH w/tools. Tagged PBTD @ 2609'. Run GR neutron log. TIH w/1-1/4" tbg. Tagged float collar @ 2609'. Press tstd to 2500 psi. Would not hold. Leak in nipple between 4-1/2" tbg head & 3-1/2" csg. NDBOP & cut off nipple. Re-weld 4-1/2" x 3-1/4" csg. NDBOP. TIH w/1-1/4" tbg. Press tst to 2500 psj. 10 mins. Held o.k. Roll hole w/2% KCl wtr. OCTI the foregoing is true, and correct 18. I hereby certify TITLE Senior Regulatory Analyst (CCEPTET SIGNED (This space for Federal or State office use) OCT 1 5 1985 TITLE APPROVED BY CONDITIONS OF APPROVAL, IF ANY: FARMINGTON RESOURCE AREA MINIO CC Imm *See Instructions on Reverse Side