

PAN AMERICAN PETROLEUM CORPORATION

P. O. Box 480, Farmington, New Mexico
February 21, 1966

File: E-68-400.1

Subject: Packer Leakage Test
Stedje Gas Com No. 1
Flora Vista Mesaverde-
Basin Dakota Field Well
San Juan County, New Mexico

Mr. E. C. Arnold
New Mexico Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico

Dear Sir:

In reference to your letter of February 16, 1966, the annual Packer Leakage Test for 1965 on the Stedje Gas Com No. 1 27-30-12 failed and it was necessary to conduct a workover to repair this leak. Copies of NMOCC Form C-103, Notice of Intent to Repair Well, were filed December 7, 1965 and approved by you on December 8, 1965.

Repairs due to tubing leaks in the Dakota tubing string were made as shown on the attached Forms C-103, Subsequent Report of Remedial Work, dated February 21, 1966. The well is now on packer leakage test following this workover and indications are that a successful packer leakage test will be conducted. Upon completion this packer leakage test report will be filed as soon as possible.

Yours very truly,

PAN AMERICAN PETROLEUM CORPORATION



L. O. Speer, Jr.
Area Superintendent

FHH:en
Attach.

