

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Fe			
Lease No. 076934				
Unit E 1	/2 300. 19			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.	 SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	 SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	 SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	 SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	 SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	 SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

				DA Y	19.54
Well No. 1 is located	1 100 ft. fro	m line a	nd _350 ft. from	$ \mathbf{E} $ line of	sec
SE 1/5 300 19 (% Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)		
(Field)	(Count	y or Subdivision)		State or Territory)	

The elevation of the derrick floor above sea level is 6013 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed world to the cleaned out to TD 5260, with packer set in 5 1/2" casing

at 1875'. The interval 1950 to 5260 was sand-oil treated with 8670 gals. diesel & 6500% send. Breakdown 1500%, treated 2000%, maximum 2500%, average injection rate 9.4 MPM. Cleaned out to 5260, no appreciable increase in gas. Bridge plug was then set at 1568 & 5 1/2" casing perforated at the following intervals: 1516-1528 w/48 Kome shote & 24 bullete, hi66-1488 w/96 Komes & 18 bullete, hi395-hh20 w/96 Komes & 50 bullete, hi66-1380 w/48 Komes and 28 bullete. Packer was then set at 1315 & the perforated intervals sand-oil treated with 7560 gallons diesel and 1000% sand. Breakdown 1800%, treated 1700%, maximum 2150%, average injection rate 7.2 BPM. Hole was cleaned out to 1568 with no increase in gas. Bridge plug at 1568 was drilled and hole cleaned out to 5260, 2 1/2" EUE tubing landed at 5148. Tree set and well shut in.

I understand that this plan of work must receive approval in writing by the	Geological Survey before operations may be stranged to
Company Belbi 011 Corporation	Act 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Address Box 1175	EFP 10 Com
Farsington, New Yorkico	By Manuell of Olsi.
	Title Supt.
U. S. GOVERNMENT PRINTING OFFICE	16-8437-5

the state of the s

on the company of the contraction of the contracti

and for the control of the control of the second of the control of the control of the control of the control o The control of the control of

•

en en de la companya La companya de la co

and the second second of the s