- 17. NU flow-back manifold. Begin immediate flow-back on 1/2" Choke (minimum of 12-Hrs), switch to 1/2" Choke, minimum total flow-back time of 36-Hrs. ND Frac valve.
- 18. TIH w/3-7/8" mill on the and CO SD, from Menefee/MV Frac, and DO CIBP @ 4500'.
- 19. Com. TIH w/ 3-7/8" mill on the and CO SD, from Point Lookour/MV Frac, to PBTD.
- 20. TOOH w/ mill and string float on thg.
- 21. TIH w/ expendable check, 1-Jt 2-3/8" tbg, 'P' Nipple on 2-3/8" production tbg, land tbg hanger, secure lock-downs.
- 22. NU WH. Pump 5-Bbls of 1% KCl wir down tbg, drop ball, and pump out expendable check.
- 23. RD and MO Big 'A' daylight completion rig.