NONTHWEST NEW MEXICO PACKER-LEAKAGE TEST

| | | | | | | | Well |
|--|-----------------|---|---|--------------------------------------|---|------------------|--|
| Operator | | Tenneco O | il Company | Lea | as e _ | Florance | No8 |
| Location | | _ | | | | | |
| of Well: | Unit | N_Sec | 14 Twp | 30 Rge | •9 | County | San Juan Prod. Medium (Tbg. or Csg.) |
| | | | | Type of Prod. | Method | of Prod. | Prod. Medium |
| | Nam | e of Reser | rvoir or Pool | (Oil or Gas) | (Flow or | Art. Lift) | (Tbg. or Csg.) |
| Upper | | W W- | 1 - | 0.4 | | | |
| Completion | <u>n </u> | mesa ve | rde | GAs | | Flow 3 | Casing |
| Lower | | Dakota | | C2.0 | | C3 | T 1 - 2 |
| Completion | n | Dakota | DITE I | Gas LOW SHUT-IN PRE | CIEDE DATA | FIOW | Tubing |
| F- 10- | - 404 - | 2.460.460 | | | | 5 S • | Stabilized? |
| Upper Hou | r, date | 3/28/83 | time chi | of t-in 72 hours | | | (Yes or No) ves |
| Compl Si Lower Hou | nut-in | 12:00 p | I anoth | of | SI pre | | Stabilized? |
| Compl S | r, uate | 12:00 n | m time shi | t-in 72 hours | | | (Yes or No) no |
| | | | | FT.OW TEST NO | .] | | |
| Commenced | at. (ho | ur. date) | * 3/31/83 | 1.00 p m | Zone p | roducing (Uppe | r or Lower): lower |
| Time | La | psed time | 7 Pres | sure 1 | Prod. Zone | 3 (1.1 | , lowel |
| (hour, da | te) | since* | Upper Compl. | Lower Compl. | Temp. | Rem | arks |
| 4/1/83 | | | | | | | |
| 11:00 a. | m. 2 | 2 hours | 260_ | 320 | | | |
| 4/2/83 | | | | | | | |
| 11:00 a. | m 4 | 6 hours | 260 - | 300 | | | |
| | | | | | | | |
| | | | | | | | |
| | - | | | | | | |
| | | | ļ | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| <u> </u> | | dissing to | <u> </u> | | | <u> </u> | |
| Froduction | n rate | aaring ce | sead on ' | Rhle in | H۳۰ | s. Gra | v. GOR - |
| 011: | 1 7 | BOFD 0; | MCTPD. Tested | Bbls. in thru (Orifice o | r Meter). | Meter | |
| Gas: | 1/ | - | MTD_T | EST SHUT-IN PRE | SSUBE DATA | | |
| Upper Hou | - date | | Length | | SI pre | | Stabilized? |
| Compl _S | hut-in | | time shu | | psig | | (Yes or No) |
| Lower Hou | | | Length | | | | Stabilized? |
| Compl S | | | | | | | |
| | nut-in | | time shu | | psig | | (Yes or No) |
| | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Commenced | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Cormenced Time | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Cormenced Time (hour, da | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Cormenced Time (hour, da | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Cormenced Time (hour, dat | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Cormenced Time (hour, da | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Cormenced Time (hour, da | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Cormenced Time (hour, da | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Cormenced Time (hour, da | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Cormenced Time (hour, dat | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Cormenced Time (hour, da | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Cormenced Time (hour, da | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Commenced Time (hour, da | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| Cormenced Time (hour, da | | | | t-in FLOW TEST NO | psig | | (Yes or No) |
| | at (ho La te) s | ur, date) | Pres | st-in FLOW TEST NO sure Lower Compl. | psig 2 JZone p Prod. Zone Temp. | roducing (Uppe | (Yes or No) r or Lower): arks |
| | at (ho La te) s | ur, date) | Pres | st-in FLOW TEST NO sure Lower Compl. | psig 2 JZone p Prod. Zone Temp. | roducing (Uppe | (Yes or No) r or Lower): arks |
| | at (ho La te) s | ur, date) | Pres | st-in FLOW TEST NO sure Lower Compl. | psig 2 JZone p Prod. Zone Temp. | roducing (Uppe | (Yes or No) r or Lower): arks |
| | at (ho La te) s | ur, date) | Pres | t-in FLOW TEST NO | psig 2 JZone p Prod. Zone Temp. | roducing (Uppe | (Yes or No) r or Lower): arks |
| | at (ho La te) s | ur, date) | Pres | st-in FLOW TEST NO sure Lower Compl. | psig 2 JZone p Prod. Zone Temp. | roducing (Uppe | (Yes or No) r or Lower): arks |
| Production Cil: Gas: | at (ho La te) s | ur, date) | Pres | st-in FLOW TEST NO sure Lower Compl. | psig 2 JZone p Prod. Zone Temp. | roducing (Uppe | (Yes or No) r or Lower): arks |
| Production Cil: Gas: FEMARKS: | at (ho La te) s | ur, date) psed time ince ** during te | Pres Upper Compl. Stased on MOTPD; Tested | Bbls. in thru (Orifice | psig 2 Zone p Prod. Zone Temp. Hrs. or Meter): | roducing (Uppe | (Yes or No) r or Lower): arks GOR |
| Production Cil:Gas:REMARKS: | at (ho La te) s | ur, date) psed time ince ** during te | Pres Upper Compl. Stased on MOTPD; Tested | Bbls. in thru (Orifice | psig 2 Zone p Prod. Zone Temp. Hrs. or Meter): | roducing (Uppe | (Yes or No) r or Lower): arks |
| Production Cil: Gas: RAMARKS: | at (ho La te) s | ur, date) psed time ince ** during temporary BOPD by | Pres Upper Compl. st ased on MCTPD; Tested | Bbls. in thru (Orifice | psig 2 | Grave | (Yes or No) r or Lower): arks GOR |
| Production Cil: Gas: RAMARKS: | at (ho La te) s | ur, date) psed time ince ** during temporary BOPD by | Pres Upper Compl. st ased on MCTPD; Tested | Bbls. in thru (Orifice | psig 2 | Grave | (Yes or No) r or Lower): arks GOR |
| Production Cil: Gas: RAMARKS: | at (ho La te) s | ur, date) psed time ince ** during temporary BOPD by | Pres Upper Compl. st ased on MCTPD; Tested | Bbls. in thru (Orifice | psig 2 | Grave | (Yes or No) r or Lower): arks GOR |
| Production Cil: Gas: RAMARKS: Approved: New Mexi | at (ho La te) s | ur, date) psed time ince ** during te: | Pres Upper Compl. st ased on MCTPD; Tested | Bbls. in I thru (Orifice Ey | psig 2 | Grave | (Yes or No) r or Lower): arks GOR |
| Production Cil: Gas: AHMARKS: Movledge Approved: New Mexi | at (ho La te) s | ur, date) psed time ince ** during te: | Pres Upper Compl. st ased on MCTPD; Tested | Bbls. in I thru (Orifice Ey | psig 2 | Grave | (Yes or No) r or Lower): arks GOR |
| Production Cil: Gas: RAMARKS: Approved: New Mexi | at (ho La te) s | ur, date) psed time ince ** during te: | Pres Upper Compl. st ased on MCTPD; Tested | Bbls. in I thru (Orifice Ey | psig 2 | Grave | (Yes or No) r or Lower): arks GOR |
| Production Cil: Gas: AHMARKS: I hereby knowledge Approved: New Mexi By | at (ho La te) s | ur, date) psed time ince ** during te: | Pres Upper Compl. st ased on MCTPD; Tested | Bbls. in thru (Orifice Ey | psig 2 Zone pi Prod. Zone Temp. Hrs. or Meter): Agen | Grave | (Yes or No) r or Lower): arks GOR |

- 1. A packer leakage test shall be commenced on each multiply cospleted well within seven days after actual completion of the well, and somusity thereafter as prescribed by the order suthorizing the multiple completion. Buch tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tubing have been disturbed. Tests shall also be taken at any time that communication is suspected or when requested by the Commission.
- 2. At least 72 hours prior to the commencement of any packer leakage test; the operator shall notify the Commission in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3. The packer leakage test shall commence when both zones of the dual completion are sbut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided however that they need not remain sbut-in sore than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: If, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.
- 5. Following completion of Flow Test No. 1, the well shall again be shutin, in accordance with Paragraph 3 above.
- 8. Flow Test No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedure for Flow Test No. 2 is to be the same as for Flow Test No. 1 except that the previously produced zone shall re main shut-in while the zone which was previously shut-in is produced.

- 7. Prossures for gas-zone tests must be measured on each zone with a decadwright pressure gauge at time intervals as follows: 3-hour tests: immediately prior to the beginning of each flow-period, at fifteen-minute intervals during the first hour thereof, and at hourly intervals thereafter, including one pressure measurement immediately prior to the conclusion of each flow period. 7-day tests: immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test
- 24-Nour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges, the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.
- 8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico Oil Conservation Commission on Northwest New Mexico Packer Leakage Test Form Revised 11-1-58, with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only). A pressure versus time curve for each zone of each test shall be constructed on the reverse side of the Packer Leakage Test Form with all deadweight pressure points taken indicated thereon. For oil zones, the pressure curve should also indicate all key pressure changes which may be reflected by the recording gauge charts. These key pressure changes should also be tabulated on the front of the Packer Leakage Test Form.

