

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Federal <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Grahamling C
9. Well No. 2 (OWWC)
10. Field and Pool, or Wildcat Blanco Mesa Verde
12. County San Juan

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator El Paso Natural Gas Company
3. Address of Operator Box 990, Farmington, New Mexico
4. Location of Well UNIT LETTER N 890 FEET FROM THE South LINE AND 1550 FEET FROM THE West LINE, SECTION 14 TOWNSHIP 30N RANGE 10W NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 6500' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Workover, Case Cement, Frac <input checked="" type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In order to increase production it is planned to workover and restimulate this well in the following manner:

Pull tubing and clean out to 5505'.

Run a full string of 2 7/8" casing and cement with approximately 175 sacks of cement.

Selectively perforate and sand water fracture the Mesa Verde formation.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Emory Wood</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>7-2-68</u>
APPROVED BY <u>Emory Wood</u>	TITLE <u>Sup Dist III</u>	DATE <u>7-2-68</u>
CONDITIONS OF APPROVAL, IF ANY:		