

Form 9-331  
(May 1963)

UNITED STATES  
DEPARTMENT OF THE INTERIOR



SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.



SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

El Paso Natural Gas Company

3. ADDRESS OF OPERATOR

Box 990, Farmington, New Mexico - 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

890'S, 1550'W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6500' OL

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Grenbling C

9. WELL NO.

2 (OWO)

10. FIELD AND POOL, OR WILDCAT

Blanco Mesa Verde

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 14, T-30-N R-10-W

N.M.P.M.

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☒  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other) Workover, Case Cement

☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐

REPAIRING WELL

☐  
☐  
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

In order to increase production it is planned to workover and restimulate this well in the following manner:

Pull tubing and clean out to 5505'.

Run a full string of 2 7/8" casing and cement with approximately 175 sacks of cement.

Selectively perforate and sand water fracture the Mesa Verde formation.

RECEIVED

JUL 2 1968

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N.M.



CONFIDENTIAL

applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local specific instructions.

applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local specific instructions.

andon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. nd reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and ethod of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site on looking to approval of the abandonment.