
		UNITED STATES MENT OF THE INTERI	OR verse side)	Budget Bureau  5. LEASE DESIGNATION A	No. 42-R1424.
		SEOLOGICAL SURVEY	İ	N. M. 05859	
	SUNDRY NOTI	6. IF INDIAN, ALLOTTEE OF TRIBE NAME			
<u>.                                    </u>				7. UNIT AGREEMENT NAM	E
	OIL GAS OTHER	L. W. Swarts			
2.	NAME OF OPERATOR	8. FARM OR LEASE NAME			
	Clinton Oil Company	N. E. Hogback Unit			
3.	ADDRESS OF OPERATOR		9. WELL NO.		
	P. O. Box 2434, Cas	per, Wyoming 8260	01	18 10. FIELD AND POOL, OR WILDCAT	
- 1	LOCATION OF WELL (Report location cl See also space 17 below.)				
	At surface		Horseshoe Gallup 11. sec., T., B., M., OR BLK. AND		
	•		SUBVEY OR AREA		
	660' FSL & 1980' FW	Sec . 13-T30N-R16W			
14.	PERMIT NO.   15. ELEVATIONS (Show whether DF, RT, GR, etc.)			12. COUNTY OR PARISH	13. STATE
				San Juan	N. M.
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data				
	NOTICE OF INTENTION TO:			QUENT REPORT OF:	
	TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	CLL .
	FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CAS	<del></del>
	SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMEN	' <u>X</u>
	REPAIR WELL	CHANGE PLANS	(Other)(Note: Report results	of multiple completion o	n Well
	(Other)		Completion or Recomple	etion Report and Log form	a.)
17.	DESCRIBE PROPOSED OR COMPLETED OPE proposed work. If well is directio nent to this work.) *	nally drilled, give subsurface local	tions and measured and true vertica	l depths for all markers	and sones perti-
	-1 1 1 40101 006	·			
	Plug back 4013' - 382	20 111111 54114 1 0 011	Age 1		
	Plug back 4013' - 382 Place top rubber cem		ridge /		
		nent plug on top of b	ridge /		
	Place top rubber cem Spot 15 sks. cement	nent plug on top of b 3820' - 3700'		a	
	Place top rubber cem Spot 15 sks. cement 3 Shoot 5 1/2" csg. @ 2	nent plug on top of b 3820' - 3700' 2800'	ridge SEP 1 0 197	4	
	Place top rubber cem Spot 15 sks. cement 3 Shoot 5 1/2" csg. @ 2 Spot 25 sk. plug 2850	nent plug on top of b 3820' - 3700' 2800'	SEP 1 0 197		
	Place top rubber cem Spot 15 sks. cement 3 Shoot 5 1/2" csg. @ 2	nent plug on top of b 3820' - 3700' 2800' ' - 2750'			

Spot 30 sk. plug 730' - 630' Spot 20 sk. plug 216' - 166' Place 10 sk. surface plug Install hole marker



18. I hereby certify that the foregoing is true and correct SIGNED Min B. Barrier	TITLE Production Engineer	DATE September 6, 1974
(This space for Federal or State office use)		
APPROVED BY CONDITIONS OF APPROVAL IF ANY:	TITLE	DATE