



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

BRUCE KING
GOVERNOR

LARRY KEHOE
SECRETARY

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

November 9, 1981

Mr. Wayne L. Peterson
Amoco Production Company
501 Airport Drive
Farmington NM 87401

Re: Sullivan Gas Com C #1E, J-28-29N-10W

Dear Mr. Peterson:

A bradenhead retest on the above-referenced well indicates a definite casing failure. In order to ensure the protection of hydrocarbon bearing and fresh water zones, you are hereby directed to initiate remedial action within thirty days.

Retests on the Snyder Gas Com B #1 and the E. E. Elliott A #1 indicate communications between the intermediate and production casing. As long as these are contained within the intermediate they may be produced in this manner; however, they should be monitored annually.

Yours truly,

Charles Gholson
Deputy Inspector

CG:gc

cc: Reading file
Dick Stamets, Santa Fe
Operator file
Well files

L-15-30-9