

from 445' to 545' and an inside plug from 135' to surface;
shut in well; WOC.

10. ND BOP and cut off wellhead below ground level and install dry hole marker. RD and MOSU. Restore location.