

Southwest Production Co.

Fannie ward #1 Unit K, 18-30N-11W API# 30-045-09481

P&A according to procedure,

Environmental

Remove all surface equipment, tank and two
treater/seperator units

Open two old pits, one by the tank and one by the wellhead

Move 20 Yards of soil

Take two samples, BTEX/TPH

~~ADD~~ ^{Pit} Collect info on
Wright ST well P&A marked