

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.  
SF 081299-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME J. J. Lommori "A"
2. NAME OF OPERATOR Clinton Oil Company	8. FARM OR LEASE NAME NE Hogback Unit
3. ADDRESS OF OPERATOR P. O. Box 2434 - Casper, Wyoming 82601	9. WELL NO. 15
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  1980' FSL and 660' FWL	10. FIELD AND POOL, OR WILDCAT Horseshoe Gallup
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 13-T30N-R16W
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5370' GL	12. COUNTY OR PARISH San Juan
	13. STATE N. Mexico

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☒CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Casing: 8-5/8" - set at 215' w/160 sacks cement  
5-1/2" - set at 3993' w/ 130 sacks cement

Perf: 3730'-3766' Upper Gallup  
3826'-3858' Lower Gallup

Propose to plug back with sand from PBTD - 3958'-3700'

Place 15 sack cement plug from 3700'-3580'

Shoot off 5-1/2" casing. Pull and lay down.

Place 25 sack cement plug 50' inside and 50' above 5-1/2" casing stub

Place 50 sack cement plug 2190'-2040' (Pt Lookout 2090'-2407')

Place 30 sack cement plug 590'-490' (Menefee 530'-2090')

Place 20 sack cement plug 215'-165'

Place 10 sack cement plug 30'-GL

Install dry hole marker

Clean up location



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side