Submit 3 ipies to

State of New Mexico Energy, Minerals and Natural Resources

Form C-103 Revised 1-1-89

Appropriate	Energy, winteral	is and mate	iai i (Coodioco	/	Nevisca i	-1-03	
ا ا ا الاستان ا	OIL CONSER	RVATIO	N DIVISION /	WELL API NO.			
P.O. Box 1980, Hobbs, NM					2004500504		
DISTRICT II	Santa Fe, Ne	w Mexico 8	37504-2088	C. Indianta Tou	3004509534		
P.O. Drawer DD, Artesia, NM 882	10			5. Indicate Typ	STATE	FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM				6. State Oil &	Gas Lease No.	TLE [
, ,				0.00000.00	B-11479		
SUNDE	RY NOTICES AND REPORT	TS ON WELLS					
OO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					7. Lease Name or Unit Agreement Name		
	SERVOIR. USE "APPLIC M C-101) FOR SUCH PR		PERMIT"				
Type of Well:					State Com B		
OIL GAS WELL WELL	ОТН	IER					
2. Name of Operator		Attention			8. Well No.		
AMOCO PRODUCTION COMP	ANY "	Gail M. Jefferson			# 3		
5 5 5 5 5			200) 000 (157	9. Pool name			
P.O. Box 800 Denver	Colorado	80201 (303) 830-6157		Blanco Mesaverde		
4. Well Location Unit Letter A:	990 Feet From The	NORT	H Line and	990 Feet Fr	om The EAST	Line	
			Line and		om me		
Sectio 16	Township	30N I	Rang 9W	NMPM	SAN JUAN	County	
	10. Elevatio	n (Show whet	her DF, RKB, RT, GR, etc	.)		a. Walaka z	
	a mathiae dipty						
44	i-t- Dt- I-			- 04 D - 1	Andrea, er sam sam skull af ar et nyke ha masen ye ta bir um		
	ppropriate Box to inc NTENTION TO:	dicate Natu	re of Notice Report o	r Otner Data JBSEQUENT R	EDODT OF		
NO 1102 OF 11			30	BSEQUENT R	EPORT OF.		
PERFORM REMEDIAL WORK	PLUG AND ABANI	OON [REMEDIAL WORK		ALTERING CASING		
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLIN	G OBNS	DI LIC AND ADAMO		
	CHANGE FEARS	لــا	COMMENCE DIVIELIN	G OFNS.	PLUG AND ABANDO	JNMENT	
PULL OR ALTER CASING			CASING TEST AND C	EMENT JOB			
OTHER: Perf and F	rac/Add Pay	X	OTHER:				
12. Describe Proposed or Complete	d Operations (Clearly sta	ate all nertiner	at details, and give pertine	at dates including	estimated date of start	ina any	
proposed	a operations (ordarly of	an peranor	it detaile, and give pertiner	n dates, moldang t	samutou date or start	ing any	
Amoco Production Company reques	sts permission to perf and	d frac the abo	ve referenced well per the	attached procedure	es.		
If you have any technical questions	nlagge contact Mark Vo.	manaki ot (201	1) 930 5944 or Coil Iofford				
if you have any technical questions	please contact Mark Tar	nasaki at (503	o) 030-3041 of Gall Jeners	on for any administ	trative concerns.		
					1 1 1 1 1 1 1 1 1 1 1 1		
				901	2 7 1993 1		
				Line All it	- 1-17		
				~m 0	ani, Div		
				当。自民の	(174 년 년 (1811년 - 181		
				***	AL Augo		
I hereby certify that the information	above is true and comp	lete to the bes	•				
SIGNATURE Yaul W.	yffeisin	/	Sr. Admi	n. Staff Asst.	04-24-	1998	
						0.0457	
TYPE OR PRINT NAME	Gail M. Jefferson			TELEPH	one no. (303) 38	U-b15/	
(This space for State							

ORIGINAL SIGNED BY ERNOL DE SET

APPROVED BY

State Com B #3 TI) = 5247' PBTD = 5177' Page 2 of 2

- 1. Check anchors. MIRUSU.
- 2. Check and record tubing, casing and bradenhead pressures.
- 3. Blow down wellhead, kill if necessary.
- 4. Nipple down wellhead, nipple up and pressure test BOP.
- 5. Tag and Tally OH with 2.375" tubing.
- 6. TIH with CIBP set @ 4530'. Pressure test Casing to 1000 psi.
- 7. RU HES Wireline Unit and Packoff.
- 8. Log Mesa Verde interval with CBL/GR/CCL to insure zonal issolation across MV. Please fax logs to (303)830-5388.
- 9. Perforate the following interval 120 deg. phasing using 3 1/8' HSC ported guns (12.5 GM, .34" EHD. 13.13 TTP, 2 SPF). Correlate with Lane Wells' GR-Neutron log dated 12/24/61: 4471-4488 4460-4466 4436-4446
- 10. Fracture Stimulate down tubing according to schedule 'A'.
- 11. Flow test well reporting Gas and Water to Denver
- 12. DO CIBP, CO to PBTD.
- 13. TIH with 2 3/8" land at 5160.
- 14. Put well on production and make money.

Orig.Completion — 5/5: Last File Update — 1/89 — by DOM

